

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
03/02/2016
Document Number:
680600481
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	412688	333536	ROY, CATHERINE	2A Doc Num:	

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		SanJuanCOGCC@bp.com	All Inspections
Beebe, Sabre		Sabre.Beebe@bp.com	All Inspections

Compliance Summary:

QtrQtr: SWSE Sec: 11 Twp: 33N Range: 8W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/30/2013	669400636	XX	ND	SATISFACTORY			No
04/29/2013	669400614	XX	ND	SATISFACTORY			No

Inspector Comment:

This is an abandoned location inspection for 067-09767 on an active well pad for wells 067-05466 and 067-06985. It does not appear that this well was drilled.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214149	WELL	PR	01/09/1963	GW	067-05466	IGNACIO 33-8 17	PR <input type="checkbox"/>
215380	WELL	PR	01/29/2003	GW	067-06985	KLUSMAN RANCHES 1	PR <input type="checkbox"/>
412688	WELL	AL	09/11/2013	LO	067-09767	KLUSMAN RANCHES GU 3	AL <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: <u> </u>	Drilling Pits: <u>1</u>	Wells: <u>2</u>	Production Pits: <u> </u>
Condensate Tanks: <u> </u>	Water Tanks: <u>1</u>	Separators: <u>2</u>	Electric Motors: <u>3</u>
Gas or Diesel Mortors: <u>2</u>	Cavity Pumps: <u>2</u>	LACT Unit: <u> </u>	Pump Jacks: <u>2</u>
Electric Generators: <u>1</u>	Gas Pipeline: <u>1</u>	Oil Pipeline: <u> </u>	Water Pipeline: <u>1</u>
Gas Compressors: <u>1</u>	VOC Combustor: <u> </u>	Oil Tanks: <u> </u>	Dehydrator Units: <u> </u>
Multi-Well Pits: <u> </u>	Pigging Station: <u> </u>	Flare: <u> </u>	Fuel Tanks: <u> </u>

Location

Predrill

Location ID: 412688

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
Agency	kerrt	Operator will comply with the BP/CDOW wildlife management plan.	04/13/2010
Agency	kubeczkod	Location is in a sensitive area because shallow groundwater; therefore either a lined drilling pit or closed loop system must be implemented.	03/19/2010
Agency	kubeczkod	Operator must implement best management practices to contain any unintentional release of fluids.	03/19/2010
Agency	kubeczkod	Location is in a sensitive area because of proximity to surface water; therefore, operator must ensure 110 percent secondary containment for any volume of fluids contained at well site during drilling and completion operations.	03/19/2010

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 412688 Type: WELL API Number: 067-09767 Status: AL Insp. Status: AL

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IRRIGATED

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: It does not appear that the well was ever drilled on the active well pad. Date _____

Overall Final Reclamation Pass Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680600482	View of project area from southeastern corner facing center. Only one BP well observed on location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3802701