



Photo 1. View of the western portion of the project area from the southwestern corner facing northward. Revegetation is comprised of smooth brome (*Bromus inermis*) and western wheatgrass (*Pascopyron smithii*).



Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward.





Photo 3. View of the eastern portion of the project area from the southeastern corner facing northward. This portion of the project area does not appear necessary for production and needs revegetation.



Photo 4. View of rill erosion occurring within the southern portion of the project area.