

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
03/10/2016
Document Number:
675102320
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>284727</u>	<u>316544</u>	<u>GRANAHAN, KYLE</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: 96850
Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
, WPX		COGCCInspectionReports@wpxenergy.com	All inspections

Compliance Summary:

QtrQtr: SWSW Sec: 16 Twp: 1S Range: 98W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/16/2014	675100511	PR	PR	SATISFACTORY			No
01/14/2010	200234773	PR	PR	SATISFACTORY			No

Inspector Comment:

Corrective actions have been implemented in regards to inspection doc # 675100511

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284727	WELL	PR	04/09/2007	GW	103-10759	FEDERAL RGU 14-16-198	PR <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
CONTAINERS	SATISFACTORY			
BATTERY	SATISFACTORY			
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: 970-285-9377

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
SEPARATOR	SATISFACTORY			
TANK BATTERY	SATISFACTORY			

Equipment:				
Type: Gas Meter Run	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment				
Corrective Action				Date:
Type: Bird Protectors	# 3	Satisfactory/Action Required:	SATISFACTORY	
Comment				
Corrective Action				Date:
Type: Deadman # & Marked	# 4	Satisfactory/Action Required:	SATISFACTORY	
Comment				
Corrective Action				Date:
Type: Plunger Lift	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment				
Corrective Action				Date:
Type: Ancillary equipment	# 2	Satisfactory/Action Required:	SATISFACTORY	
Comment	Chem totes w/secondary containment			
Corrective Action				Date:

Type: Horizontal Heated Separator	# 1	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action	Date:	

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	1	300 BBLS	HEATED STEEL AST	39.958520,-108.403810
S/AR	SATISFACTORY		Comment: AIRS ID # 103/0529/001	
Corrective Action:			Corrective Date:	

Paint

Condition	Adequate
Other (Content) _____	
Other (Capacity) _____	
Other (Type) _____	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Corrective Action			Corrective Date	
Comment				

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	2	300 BBLS	HEATED STEEL AST	,
S/AR	SATISFACTORY		Comment: Shares containment with condensate	
Corrective Action:			Corrective Date:	

Paint

Condition	Adequate
Other (Content) _____	
Other (Capacity) _____	
Other (Type) _____	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Corrective Action			Corrective Date	
Comment				

Venting:

Yes/No	NO
Comment	

Flaring:

Type	Satisfactory/Action Required
Comment:	

Corrective Action: _____	Correct Action Date: _____
--------------------------	----------------------------

Predrill

Location ID: 284727

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 284727 Type: WELL API Number: 103-10759 Status: PR Insp. Status: PR

Producing Well

Comment: PR - no leaks/venting present

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ **Date:** _____

Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:
Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: _____
Comment: _____

1003a. Waste and Debris removed? Pass
CM _____
CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass
CM _____
CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass
CM _____
CA _____ CA Date _____

Guy line anchors marked? Pass
CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION
Cropland
Top soil replaced _____ Recontoured _____ Perennial forage re-established _____
Non-Cropland
Top soil replaced _____ Recontoured _____ 80% Revegetation _____

Inspector Name: GRANAHAN, KYLE

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads _____

Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					
Ditches	Pass					

S/A/V: SATISFACTOR
Y _____

Corrective Date: _____

Comment: No sediment flow evident

CA: _____

Pits: NO SURFACE INDICATION OF PIT