

**FORM
INSP**

Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/10/2016

Document Number:

679901224

Overall Inspection:

SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	212635	324791	Welsh, Brian	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>95620</u>
Name of Operator:	<u>WESTERN OPERATING COMPANY</u>
Address:	<u>518 17TH ST STE 200</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Hart, Dale	719-688-1638	dalehartwoc@fairpoint.net	

Compliance Summary:

QtrQtr: NESE Sec: 4 Twp: 19S Range: 45W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/02/2015	679900480	PR	PR	SATISFACTORY			No
01/31/2014	668602053	PR	PR	SATISFACTORY	P		No
05/09/2011	200310298	PR	PR	SATISFACTORY			No
09/24/2010	200276776	PR	PR	ACTION REQUIRED			Yes
08/30/2010	200268910	PR	PR	SATISFACTORY			No
06/29/2010	200260003	PR	PR	ACTION REQUIRED			Yes
06/02/2010	200254542	PR	PR	ACTION REQUIRED			Yes
05/12/2010	200250566	PR	PR	ACTION REQUIRED			Yes
03/03/2010	200235281	PR	PR	SATISFACTORY			No
01/23/2009	200203003	PR	PR	ACTION REQUIRED			Yes
10/17/2006	200097974	CO	PR	SATISFACTORY	I	Pass	No
09/02/2004	200059588	PR	PR	SATISFACTORY		Pass	No
11/01/2001	200021239	CO	PR	ACTION REQUIRED			
03/20/2000	200005248	PR	PR	SATISFACTORY	I	Pass	No
11/16/1998	500144462	PR	PR			Pass	No
10/30/1996	500144461	PR	PR			Pass	No
10/19/1995	500144460	PR	PR			Pass	No
04/07/1994	500144459		PR				

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
115277	PIT		09/23/1999		-	DAWSON 1,2 & 4	
212635	WELL	PR	01/01/2014	OW	061-05143	DAWSON 1	PR

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY	Dirt road through pasture		

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY	Lease sign at tank battery		
WELLHEAD	SATISFACTORY	Lease sign by unit		
TANK LABELS/PLACARDS	SATISFACTORY	Metal signs by tanks and treater		

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
PUMP JACK	SATISFACTORY	Metal panels around unit and wellhead		
TANK BATTERY	SATISFACTORY	Metal panels on east side of battery and wire fence on west side of battery		

Equipment:				
Type: Verical Heater Treater	# 1	Satisfactory/Action Required: SATISFACTORY		
Comment				
Corrective Action				Date:
Type: Ancillary equipment	# 4	Satisfactory/Action Required: SATISFACTORY		
Comment	Electric panel, electric circ pump, bellows meter, electric water pump in shed			
Corrective Action				Date:
Type: Prime Mover	# 1	Satisfactory/Action Required: SATISFACTORY		
Comment	Electric motor			
Corrective Action				Date:
Type: Pump Jack	# 1	Satisfactory/Action Required: SATISFACTORY		
Comment	American unit			
Corrective Action				Date:
Type: Deadman # & Marked	# 4	Satisfactory/Action Required: SATISFACTORY		
Comment				
Corrective Action				Date:

Facilities:	<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST	38.429220,-102.455140
S/AR	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:

<u>Paint</u>				
Condition				
Other (Content)	_____			
Other (Capacity)	_____			
Other (Type)	_____			

<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Corrective Action				Corrective Date
Comment	Shared berms			

Facilities:	<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS
CRUDE OIL	3	400 BBLS	STEEL AST	38.429220,-102.455140
S/AR	SATISFACTORY		Comment:	Manhole cover on north oil tank removed. Tank is not in use
Corrective Action:				Corrective Date:

<u>Paint</u>				
Condition				
Other (Content)	_____			

Inspector Name: Welsh, Brian

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Comment	
---------	--

Venting:

Yes/No	YES
--------	-----

Comment	2" Casing vent. Valve closed to vent
---------	--------------------------------------

Flaring:

Type	Satisfactory/Action Required
------	------------------------------

Comment:	
----------	--

Corrective Action:		Correct Action Date:	
--------------------	--	----------------------	--

Predrill

Location ID: 212635

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: SATISFACTORY **Comment:** No COAs

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 212635 Type: WELL API Number: 061-05143 Status: PR Insp. Status: PR

Producing Well

Comment: Producing. Tank battery is 950' SE @ 38.429220/-102.455140

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? Pass

CM _____
CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____
CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass

CM _____
CA _____ CA Date _____

Guy line anchors marked? Pass

CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

S/A/V: SATISFACTOR Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT