

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/11/2016

Document Number:

679901229

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

|                     |             |        |                 |                    |                          |
|---------------------|-------------|--------|-----------------|--------------------|--------------------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | <input type="checkbox"/> |
|                     | 416590      | 416599 | Welsh, Brian    | 2A Doc Num:        |                          |

**Operator Information:**OGCC Operator Number: 55575Name of Operator: MCELVAIN ENERGY INCAddress: 1050 17TH ST STE 2500City: DENVER State: CO Zip: 80265-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name  | Phone                     | Email              | Comment |
|---------------|---------------------------|--------------------|---------|
| Powell, Debby | 303-893-0933<br>off/10066 | debby@mcelvain.com |         |

**Compliance Summary:**QtrQtr: SESE Sec: 18 Twp: 2S Range: 46W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 12/19/2014 | 668500730 | PR         | PR          | SATISFACTORY                  | I        |                | No              |
| 09/02/2011 | 200320181 | PR         | PR          | SATISFACTORY                  |          |                | No              |
| 09/02/2011 | 200320182 | PR         | PR          | SATISFACTORY                  |          |                | No              |

**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 416590      | WELL | PR     | 03/30/2011  | GW         | 125-11829 | Maroon 18-16  | PR          | <input checked="" type="checkbox"/> |

**Equipment:****Location Inventory**

|                                     |                                |                             |                                 |
|-------------------------------------|--------------------------------|-----------------------------|---------------------------------|
| Special Purpose Pits: <u>      </u> | Drilling Pits: <u>1</u>        | Wells: <u>1</u>             | Production Pits: <u>      </u>  |
| Condensate Tanks: <u>      </u>     | Water Tanks: <u>      </u>     | Separators: <u>1</u>        | Electric Motors: <u>      </u>  |
| Gas or Diesel Mortors: <u>1</u>     | Cavity Pumps: <u>      </u>    | LACT Unit: <u>      </u>    | Pump Jacks: <u>1</u>            |
| Electric Generators: <u>      </u>  | Gas Pipeline: <u>1</u>         | Oil Pipeline: <u>      </u> | Water Pipeline: <u>1</u>        |
| Gas Compressors: <u>      </u>      | VOC Combustor: <u>      </u>   | Oil Tanks: <u>      </u>    | Dehydrator Units: <u>      </u> |
| Multi-Well Pits: <u>      </u>      | Pigging Station: <u>      </u> | Flare: <u>      </u>        | Fuel Tanks: <u>      </u>       |

**Location**

Inspector Name: Welsh, Brian

| <b>Lease Road:</b> |                              |                           |                   |      |
|--------------------|------------------------------|---------------------------|-------------------|------|
| Type               | Satisfactory/Action Required | comment                   | Corrective Action | Date |
| Access             | SATISFACTORY                 | Two track through pasture |                   |      |

| <b>Signs/Marker:</b> |                              |                          |                   |         |
|----------------------|------------------------------|--------------------------|-------------------|---------|
| Type                 | Satisfactory/Action Required | Comment                  | Corrective Action | CA Date |
| WELLHEAD             | SATISFACTORY                 | Lease sign by metal shed |                   |         |

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

| <b>Good Housekeeping:</b> |                              |         |                   |         |
|---------------------------|------------------------------|---------|-------------------|---------|
| Type                      | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|                           |                              |         |                   |         |

| <b>Spills:</b>   |      |        |                   |         |
|--|------|--------|-------------------|---------|
| Type   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

| <b>Fencing/:</b> |                              |  |                   |         |
|------------------|------------------------------|--|-------------------|---------|
| Type             | Satisfactory/Action Required | Comment  | Corrective Action | CA Date |
| WELLHEAD         | SATISFACTORY                 | Metal panels around wellhead, metal shed and VGS |                   |         |

| <b>Equipment:</b> |   |                               |  |       |
|-------------------|---|-------------------------------|--|-------|
| Type:             | # | Satisfactory/Action Required: |  |       |
| Comment           |   |                               |  |       |
| Corrective Action |   |                               |  | Date: |

| <b>Venting:</b> |    |
|-----------------|----|
| Yes/No          | NO |
| Comment         |    |

| <b>Flaring:</b>    |  |                              |  |
|--------------------|--|------------------------------|--|
| Type               |  | Satisfactory/Action Required |  |
| Comment:           |  |                              |  |
| Corrective Action: |  | Correct Action Date:         |  |

**Predrill**

Location ID: 416590

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

S/AR: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

S/AR: SATISFACTORY

Comment: No COAs

CA: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 416590 Type: WELL API Number: 125-11829 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing. Casing production. Not flowing at time of inspection

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

Inspector Name: Welsh, Brian

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: Welsh, Brian

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

S/A/V: SATISFACTOR

Corrective Date: \_\_\_\_\_

Y

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT