



Photo#1: Overview of Location to West.



Photo#2: Pipe stored on West side next to Facilities.

March 6, 2016

Inspection Photos BLK Hills PR Loc# 312741



Photo#3: More pipe moved onto East side of Location since previous Inspection.





Photo#4: More Pipe storage, view to NE.



Photo#5: Pipe stored along North Berm



Photo#6: Drain out of Location at Mid North Berm.

March 6, 2016

Inspection Photos BLK Hills PR Loc# 312741