

# Interim Reclamation Inspection

3/10/2016

Operator: Noble Energy

Location: 432353


Weld County, CO

SESW Section 22 T9N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



**Figure 1:** Photo of well.





**Figure 2:** Photo taken from the north end of the interim area. Photo shows interim area composed predominantly with undesirable weedy vegetation.





**Figure 3:** Photo taken from the northeast corner of the interim location, facing west. Photo shows vegetation on interim area.





**Figure 4:** Photo taken from the northeast corner of the interim location, facing south. Photo shows vegetation on interim area.





**Figure 5:** Photo taken from the east end of the interim area, facing west. Photo shows vegetation not uniformly distributed, and predominantly undesirable weedy plant species.





**Figure 6:** Photo east of location. Photo shows vegetation on reference area.





**Figure 7:** Photo taken from the southeast corner of the interim location, facing north. Photo shows vegetation on interim area.





**Figure 8:** Photo taken from the southeast corner of the interim location, facing west. Photo shows vegetation on interim area.





**Figure 9:** Photo taken from the southern end of the interim area, facing north. Photo shows vegetation not uniformly distributed, and predominantly undesirable weedy plant species.





**Figure 10:** Photo taken from the southwest corner of the location, facing east. Photo shows interim area.





**Figure 11:** Photo taken from the southwest corner of the location, facing north. Photo shows interim area.





**Figure 12:** Photo taken from the northwest corner of the location, facing south. Photo shows interim and project areas.





**Figure 13:** Photo taken from the northwest corner of the location, facing south. Photo shows interim and project areas.