

Interim Reclamation Inspection

3/11/2016

Operator: Noble Energy

Location ID: 432108

Weld County, CO

NWNW Section 36 T9N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



Figure 1: Photo of well and sign.



Figure 2: Photo taken from the southeast corner of the location, facing north. Photo shows vegetation on the interim area. Note large patches of undesirable weedy vegetation.



Figure 3: Photo taken from the southeast corner of the location, facing west. Photo shows vegetation on the interim area.



Figure 4: Photo taken from the southern end of the interim area. Photo shows vegetation in process. Interim area has not achieved uniform distribution.



Figure 5: Photo taken from the southwest corner of the location, facing east. Photo shows interim and project areas.



Figure 6: Photo taken from the southwest corner of the location, facing north. Photo shows interim and project areas.



Figure 7: Photo taken from the western end of the location, facing north. Photo shows the interim predominantly composed of undesirable weedy vegetation.



Figure 8: Photo taken from the northwest corner of the location, facing south. Photo shows interim and project areas.



Figure 9: Photo taken from the northwest corner of the location, facing east. Photo shows the northern interim area.



Figure 10: Photo taken from the northeast corner of the location, facing west. Photo shows vegetation on the interim area. Note large patches of undesirable weedy vegetation.



Figure 11: Photo taken from the northeast corner of the location, facing south. Photo shows vegetation on the interim area. Note large patches of undesirable weedy vegetation.