

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/10/2016

Document Number:

673802955

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	327014	327014	Gomez, Jason	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	

Compliance Summary:QtrQtr: SWNE Sec: 33 Twp: 5N Range: 66W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
246209	WELL	PR	11/11/1990	OW	123-14006	LESSER-PM J33-7	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Inspector Name: Gomez, Jason

TANK LABELS/PLACARDS	SATISFACTORY			
----------------------	--------------	--	--	--

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Other	SATISFACTORY	Wire/Tank Battery/Seperator		
Other	SATISFACTORY	Fabricated Metal		

Equipment:

Type: Horizontal Heated Separator	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:
Type: Bird Protectors	# 2	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:
Type: Gas Meter Run	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:
Type: Emission Control Device	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:
Type: Plunger Lift	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<50 BBLS	CONCRETE SUMP/VAULT	40.357370,-104.782740

S/AR: SATISFACTORY Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

Condition	Adequate
-----------	----------

Inspector Name: Gomez, Jason

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
Comment			

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST	40.357370,-104.782740

S/AR	SATISFACTORY	Comment:	
------	--------------	----------	--

Corrective Action:		Corrective Date:	
--------------------	--	------------------	--

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
Comment			

Venting:

Yes/No	NO
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 327014

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 246209 Type: WELL API Number: 123-14006 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Pressure Monitored

CA: _____

CA Date: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: Gomez, Jason

Comment: <input style="width:700px" type="text"/>		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	
Water Well:		
		Lat _____
		Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____
Field Parameters:		
<input style="width:300px" type="text"/>		
Sample Location: <input style="width:400px" type="text"/>		
Emission Control Burner (ECB): Y _____		
Comment: _____		
Pilot: ON _____	Wildlife Protection Devices (fired vessels): YES _____	

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____	Date Interim Reclamation Completed: _____
Land Use: _____	
Comment: <input style="width:750px" type="text"/>	
1003a. Waste and Debris removed? <u>Pass</u>	
CM _____	
CA _____	CA Date _____
Unused or unneeded equipment onsite? <u>Pass</u>	
CM _____	
CA _____	CA Date _____
Pit, cellars, rat holes and other bores closed? <u>Pass</u>	
CM _____	
CA _____	CA Date _____
Guy line anchors marked? _____	
CM _____	
CA _____	CA Date _____
1003b. Area no longer in use? <u>Pass</u>	Production areas stabilized ? <u>Pass</u>
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____	
Subsidence over on drill pit? _____	
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____	
Production areas have been stabilized? <u>Pass</u>	Segregated soils have been replaced? <u>Pass</u>
RESTORATION AND REVEGETATION	
<u>Cropland</u>	
Top soil replaced <u>Pass</u>	Recontoured <u>Pass</u>
Perennial forage re-established _____	

Inspector Name: Gomez, Jason

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

S/A/V: SATISFACTOR Y _____

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT