



Photo#1: Overview of Location to NW.



Photo#2: View of Location to SE. Equipment/Supplies stored on Location, subject of Variance request.





Photo#3: View of Well head to North



Photo#4: Small Stockpile at East edge of Well barrier; in place long enough to grow Weed crop/now Debris.





Photo#5: Kochia has senesced and become Debris. View just off Well Head to SE



Photo#6: Sediment is building up around Well Head.



Photo#7: Facilities Located to SE of Well ; refer to Aerial view attached for juxtaposition with Well & Stored Equipment.