



00657610

LEASE INSPECTION FORMDate 10/9/84Operator DohertyField LOBOLease Name & No. Miller-RediessCounty WASHTank Battery No. 3N54 P23

Location \_\_\_\_\_

Legal Description \_\_\_\_\_

Type of Inspection PIT

Water Inflow \_\_\_\_\_ (Bbls. per Day)

RESULTS OF INSPECTION(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)  
Type of TankSKIM TANK 1- buriedPIT No. 1 30x70 trace oilPIT NO. 2 30x100 trace oil

PIT NO. 3 \_\_\_\_\_

ADDITIONAL PITS \_\_\_\_\_

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety Conditions, Etc.)

Water allowed to drain from pits via natural topography to west

RECOMMENDED ACTION (If Required) \_\_\_\_\_

INSPECTOR KTR