



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

1555 North 17th Avenue
Greeley, CO 80631



Public Health
Prevent. Promote. Protect.

www.weldhealth.org

**Health Administration
Vital Records**
Tele: 970-304-6410
Fax: 970-304-6412

**Public Health &
Clinical Services**
Tele: 970-304-6420
Fax: 970-304-6416

**Environmental
Health Services**
Tele: 970-304-6415
Fax: 970-304-6411

**Communication,
Education & Planning**
Tele: 970-304-6470
Fax: 970-304-6452

**Emergency Preparedness
& Response**
Tele: 970-304-6420
Fax: 970-304-6469

Our vision: Together with the communities we serve, we are working to make Weld County the healthiest place to live, learn, work, and play.

October 26, 2015

EOG Simba
Attn: Jason Rauen
600 17th Street
Suite 1000N
Denver, Colorado 80202

Subject: EOG Resources – Simba Facility, First Semiannual Inspection 2015

Dear Mr. Rauen:

On September 14, 2015 the Weld County Department of Public Health and Environment (WCDPHE) conducted a routine inspection of EOG Resources – Simba Class II Injection Disposal Facility, located off Weld County Road 136, Weld County, Colorado. The purpose of the inspection was to assess the facility's compliance with the Approved Site Specific Development Plan Use by Special Review Permit, USR13-0017, and applicable Weld County Code.

Based on the inspection and the documentation submitted, the facility was in compliance with USR13-0017. A copy of the inspection form is attached. If you have any questions regarding this inspection, please contact me at 970-304-6415, extension 2220.

Sincerely,

Ben Frissell
Environmental Health Specialist
WCDPHE, Environmental Health Services

ec: Bob Koehler, COGCC
Rob Patterson, EOG Resources
David Long, EOG Resources
Michelle Martin, Weld County Planning
David Snapp, CDPHE

INJECTION WELL INSPECTION REPORT CHECKLIST

FACILITY OWNER/OPERATOR: EOG

FACILITY NAME: SIMBA

FACILITY ID: 159370

USR: 13-0017

DATE: 9/14/15 INSPECTION: Q/SA

WELL CLASS: I/II

CONTACT PERSON: ROB PATTERSON

PHONE: 307-231-3653

ADDRESS: 3001 E. PERSHING BLVD
STE 100
CITYENNE, WY 82001

DAVID LONG
600 17TH ST
SUITE 1000N
DENVER, CO 80202

FACILITY LOCATION:

WGR 136 5 mile west of 77

TRUCK DELIVERIES/DAY~ 5-7

BARRELS INJECTED/DAY~ 10,000

OPEN A WEEK

INJECTION PRESSURE: 200 psi (LIMIT 1435 psi)

SOLIDS/SEDIMENT DISPOSAL NAME:

PETROLEUM CONTAMINATED SOILS: ~~ETED~~

ON-SITE STORAGE: Y/N

CONDITION OF CONCRETE RECEIVING PAD: GOOD

LEAK DETECTION SYSTEM MONITORING: Y/N - NOT SAMPLED

FREQ/RECORDS:

GROUNDWATER MONITORING WELL CONDITION: NA

REPORTS: Y/N

CHEMICALS STORED: Y/N

EMERGENCY RELEASES: Y/N

ENVIRONMENTAL SPECIALIST: BEN FRISSEN

PERSONS PRESENT AT TIME OF INSPECTION: ROB PATTERSON

CURRENT CONDITIONS/COMMENTS:

- SPEC
- GRANDFATHER MONITORING PLAN
- P. SP. SA. KAMES