

## Interim Reclamation Inspection



**Photo 1.** Photo taken from west of location, facing East. Location needs a permanent sign per Rule 210.b.



## Interim Reclamation Inspection



**Photo 2.** Photo taken from North of location, facing South. Location needs a permanent sign per Rule 210.b.



## Interim Reclamation Inspection



**Photo 3.** Photo taken from east of location, facing West. Location needs a permanent sign per Rule 210.b.



## Interim Reclamation Inspection



**Photo 4.** Photo taken from south of location, facing North. Location needs a permanent sign per Rule 210.b.