

Abandoned Location Inspection



Photo 1. Photo taken from center of location, facing West. It appears the location was never built.

Abandoned Location Inspection



Photo 2. Photo taken from center of location, facing North. It appears the location was never built.

Abandoned Location Inspection



Photo 3. Photo taken from center of location, facing East. It appears the location was never built.

Abandoned Location Inspection



Photo 4. Photo taken from center of location, facing South. It appears the location was never built.

Abandoned Location Inspection



Photo 5. Photo taken of location sign. Need to remove sign per Rule 603.f.