

Inspection Photos
3/22/16
Facility #258358
HYON 23-32 PIT




Figure 1 – Lease sign.



Figure 2 – Pit and wellhead.



Figure 3 – Discarded tubing left in pit.



Figure 4 – Wellhead looking toward pit.