

**FORM  
INSP**  
Rev  
05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
03/22/2016  
Document Number:  
674702529

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>335492</u>	<u>335492</u>	<u>LONGWORTH, MIKE</u>	<input type="checkbox"/>	

Overall Inspection:  
SATISFACTORY w/ CMT  
or AR

**Operator Information:**

OGCC Operator Number:	<u>96850</u>
Name of Operator:	<u>WPX ENERGY ROCKY MOUNTAIN LLC</u>
Address:	<u>PO BOX 370</u>
City:	<u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, WPX	970-263-2716	COGCCInspectionReports@wpxenergy.com	WPX Inspection Mail Box

**Compliance Summary:**

QtrQtr:	<u>SENE</u>	Sec:	<u>32</u>	Twp:	<u>6S</u>	Range:	<u>96W</u>
---------	-------------	------	-----------	------	-----------	--------	------------

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/02/2016	674702440			SC			No
07/29/2014	674700136			SATISFACTORY			No
06/10/2013	663801117			SATISFACTORY	I		No

**Inspector Comment:**

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
300006	WELL	PR	04/16/2011	GW	045-17818	WILLIAMS GM 644-32	PR	<input checked="" type="checkbox"/>
300007	WELL	PR	04/16/2011	GW	045-17819	WILLIAMS GM 443-32	PR	<input checked="" type="checkbox"/>
300008	WELL	PR	04/16/2011	GW	045-17820	WILLIAMS GM 544-32	PR	<input checked="" type="checkbox"/>
300009	WELL	PR	04/16/2011	GW	045-17821	WILLIAMS GM 343-32	PR	<input checked="" type="checkbox"/>
300010	WELL	PR	04/16/2011	GW	045-17822	WILLIAMS GM 523-32	PR	<input checked="" type="checkbox"/>
300011	WELL	PR	04/16/2011	GW	045-17823	WILLIAMS GM 334-32	PR	<input checked="" type="checkbox"/>
300012	WELL	PR	04/16/2011	GW	045-17824	WILLIAMS GM 444-32	PR	<input checked="" type="checkbox"/>
300013	WELL	PR	04/16/2011	GW	045-17825	WILLIAMS GM 44-32	PR	<input checked="" type="checkbox"/>
300019	WELL	PR	03/01/2012	GW	045-17829	WILLIAMS GM 34-32	PR	<input checked="" type="checkbox"/>

300020	WELL	PR	04/16/2011	GW	045-17830	WILLIAMS GM 434-32	WK	<input checked="" type="checkbox"/>
300021	WELL	PR	04/16/2011	GW	045-17831	WILLIAMS GM 344-32	PR	<input checked="" type="checkbox"/>
422637	PIT	CL	08/27/2010		-	GM 343-32	CL	<input type="checkbox"/>

**Equipment:** Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY			
BATTERY	SATISFACTORY			
CONTAINERS	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: \_\_\_\_\_  
 Comment: **970-285-9377**  
 Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Spills:**

Type	Area	Volume	Corrective action	CA Date
	WELLHEAD	<= 1 bbl	Clean up stains around well heads.	04/02/2016

Multiple Spills and Releases?

**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Equipment:**

Type:	#	Satisfactory/Action Required:	
Comment			
Corrective Action			Date: _____

<b>Venting:</b>	
Yes/No	
Comment	

<b>Flaring:</b>			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

**Predrill**

Location ID: 335492

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/AR:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

**Surface Owner Contact Information:**

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:**

\_\_\_\_\_

**Summary of Operator Response to Landowner Issues:**

\_\_\_\_\_

**Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**

\_\_\_\_\_

**Facility**

Facility ID: <u>300006</u>	Type: <u>WELL</u>	API Number: <u>045-17818</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: Producing well

Facility ID: 300007	Type: WELL	API Number: 045-17819	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Facility ID: 300008	Type: WELL	API Number: 045-17820	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Facility ID: 300009	Type: WELL	API Number: 045-17821	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Facility ID: 300010	Type: WELL	API Number: 045-17822	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Facility ID: 300011	Type: WELL	API Number: 045-17823	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Facility ID: 300012	Type: WELL	API Number: 045-17824	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Facility ID: 300013	Type: WELL	API Number: 045-17825	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Facility ID: 300019	Type: WELL	API Number: 045-17829	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Facility ID: 300020	Type: WELL	API Number: 045-17830	Status: PR	Insp. Status: WK
---------------------	------------	-----------------------	------------	------------------

**Workover**

Comment: Monument Well Service Rig 20, coming out of the hole doing a clean out on well.

Facility ID: 300021	Type: WELL	API Number: 045-17831	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:** \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_  
 DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:** \_\_\_\_\_

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**  
 Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_  
 Land Use: \_\_\_\_\_  
 Comment: \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_  
 CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_  
 CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_  
 CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? **Fail**  
 CM **Unmarked deadman on location**  
 CA **Mark or remove deadman.** CA Date **04/02/2016**

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_  
 1003 f. Weeds Noxious weeds? \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**  
 Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_  
 Final Land Use: \_\_\_\_\_  
 Reminder: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_  
 Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_  
 Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_  
 Gravel removed \_\_\_\_\_  
 Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_  
 Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_  
 Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_  
 Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_  
 Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 CA: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	422637	2213254	
	422637	2213254	

COGCC Comments		
Comment	User	Date
Inspection is a work over inspection. Corrective actions and corrective action dates are from last inspection 3/2/16 inspection 674702440. Stains at wells still remain and unmarked deadmen remain unmarked.	longworm	03/22/2016