

**FORM
INSP**

Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/24/2016

Document Number:

671106801

Overall Inspection:

SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>417529</u>	<u>317936</u>	<u>MONTOYA, JOHN</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>47120</u>
Name of Operator:	<u>KERR MCGEE OIL & GAS ONSHORE LP</u>
Address:	<u>P O BOX 173779</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80217-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCinspections@anadarko.com	All Inspections
REDDY, LUKE		Luke.Reddy@anadarko.com	ALL INSPECTIONS
Avant, Paul	720-929-6475	Paul.Avant@anadarko.com	regulatory

Compliance Summary:

QtrQtr:	<u>SWNE</u>	Sec:	<u>2</u>	Twp:	<u>1N</u>	Range:	<u>66W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/02/2012	667600087	PR	PR	SATISFACTORY			No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
240207	WELL	PR	04/19/2012	OW	123-07995	BROWN, GORDON D. UNIT 1	PR	<input checked="" type="checkbox"/>
417525	WELL	PR	05/20/2011	OW	123-31683	HIGHWAY 160 41-2	PR	<input checked="" type="checkbox"/>
417526	WELL	PR	07/13/2012	OW	123-31684	HIGHWAY 160 1-2	PR	<input checked="" type="checkbox"/>
417529	WELL	PR	05/20/2011	OW	123-31687	HIGHWAY 160 24-2	PR	<input checked="" type="checkbox"/>
417530	WELL	PR	05/17/2011	GW	123-31688	HIGHWAY 160 8-2S	PR	<input checked="" type="checkbox"/>
417533	WELL	PR	01/23/2011	GW	123-31690	HIGHWAY 160 8-2	PR	<input checked="" type="checkbox"/>
417537	WELL	PR	01/17/2011	OW	123-31691	HIGHWAY 160 7-2	PR	<input checked="" type="checkbox"/>
417539	WELL	PR	01/11/2011	OW	123-31692	HIGHWAY 160 2-2	PR	<input checked="" type="checkbox"/>
417543	WELL	PR	07/14/2011	OW	123-31693	HIGHWAY 160 1-2S	PR	<input checked="" type="checkbox"/>

417544	WELL	PR	03/12/2014	GW	123-31694	HIGHWAY 160 26-2	PR	<input checked="" type="checkbox"/>
417546	WELL	PR	05/27/2010	OW	123-31695	HIGHWAY 160 2-2S	PR	<input checked="" type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>11</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>1</u>	Separators: <u>11</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>1</u>	Oil Tanks: <u>11</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: <u>1</u>	Fuel Tanks: <u>11</u>

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	ROD IRON FENCE AROUND ALL WELLSSE CORNERN40.04988 W-104.44426		

Equipment:

Type: Plunger Lift	# 1	Satisfactory/Action Required:	
Comment			
Corrective Action		Date:	

Venting:

Yes/No	
--------	--

Comment	
---------	--

Flaring:

Type	Satisfactory/Action Required
Comment:	
Corrective Action:	Correct Action Date:

Predrill

Location ID: 417529

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 240207 Type: WELL API Number: 123-07995 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: **BRADENHEAD PLUMBED UP**
CA:
CA Date:

Facility ID: 417525 Type: WELL API Number: 123-31683 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: **BRADENHEAD PLUMBED UP**
CA:
CA Date:

Facility ID: 417526 Type: WELL API Number: 123-31684 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: **BRADENHEAD PLUMBED UP**
CA:
CA Date:

Facility ID: 417529 Type: WELL API Number: 123-31687 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: **BRADENHEAD PLUMBED UP**
CA:
CA Date:

Facility ID: 417530 Type: WELL API Number: 123-31688 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: **BRADENHEAD PLUMBED UP**
CA:
CA Date:

Facility ID: 417533 Type: WELL API Number: 123-31690 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: **BRADENHEAD PLUMBED UP**
CA:
CA Date:

Facility ID: 417537 Type: WELL API Number: 123-31691 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: BRADENHEAD PLUMBED UP

CA:

CA Date:

Facility ID: 417539 Type: WELL API Number: 123-31692 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: BRADENHEAD PLUMBED UP

CA:

CA Date:

Facility ID: 417543 Type: WELL API Number: 123-31693 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: BRADENHEAD PLUMBED UP

CA:

CA Date:

Facility ID: 417544 Type: WELL API Number: 123-31694 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: BRADENHEAD PLUMBED UP

CA:

CA Date:

Facility ID: 417546 Type: WELL API Number: 123-31695 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment:

CA:

CA Date:

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:
Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: DRY LAND

Comment: 11 WELLS ON THIS PAD
SE CORNER
N40.04988
W-104.44426

1003a. Waste and Debris removed? Pass
CM _____
CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass
CM _____
CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass
CM _____
CA _____ CA Date _____

Guy line anchors marked? _____
CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland
Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: DRY LAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

S/A/V: SATISFACTOR Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
DOCUMENT # 667600083 DATED 3/2/2012 CAPCITY ON WATER TANK, METER SHED PAINTED, WELL SIGNAGE ALL OK	montoyaj	03/24/2016