



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern portion of the interim reclamation area from the southeastern corner facing northward. Revegetation is progressing and largely comprised of soft brome (*Bromus inermis*), intermediate wheatgrass (*Thinopyron intermedium*), and crested wheatgrass (*Agropyron cristatum*).



Photo 3. View of musk thistle (*Carduus nutans*) rosette within the eastern portion of the interim reclamation area. Several of these were observed.



Photo 4. View of the southern portion of the interim reclamation area from the southeastern corner facing westward.



Photo 5. View of the western portion of the interim reclamation area from the northwestern corner facing southward.