

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/25/2016

Document Number:

674702542

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	311638	311638	LONGWORTH, MIKE	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

**Compliance Summary:**QtrQtr: NENW Sec: 4 Twp: 6S Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/30/2015	674701890			SATISFACTORY		Pass	No
09/30/2015	674701889			SATISFACTORY			No
04/27/2015	674701327			SATISFACTORY			No
01/15/2015	674700850			SATISFACTORY			No
01/14/2014	663902652			SATISFACTORY	F		No
08/12/2013	663900642			SATISFACTORY	F		No

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
282774	WELL	PR	12/01/2009	GW	045-11838	N. PARACHUTE MF07C-4 C04 696	PR	<input checked="" type="checkbox"/>
282775	WELL	PA	06/07/2007	GW	045-11837	N.PARACHUTE MF13B C04 696	PA	<input type="checkbox"/>
282776	WELL	PR	04/27/2007	GW	045-11836	N.PARACHUTE MF 13D C04 696	PR	<input checked="" type="checkbox"/>
282777	WELL	PR	04/12/2007	GW	045-11835	N. PARACHUTE MF04D C04 696	PR	<input checked="" type="checkbox"/>
282778	WELL	PR	01/23/2006	GW	045-11834	N.PARACHUTE MF02C C04 696	PR	<input checked="" type="checkbox"/>
282779	WELL	PR	01/23/2006	GW	045-11833	N.PARACHUTE MF08C C04 696	PR	<input checked="" type="checkbox"/>
282780	WELL	PR	01/23/2006	GW	045-11832	N.PARACHUTE MF03A C04 696	PR	<input checked="" type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

282781	WELL	PR	11/30/2009	GW	045-11831	N. PARACHUTE MF06C-4 C04 696	PR	<input checked="" type="checkbox"/>
282784	WELL	PR	01/23/2006	GW	045-11829	N.PARACHUTE MF08A CO4 696	PR	<input checked="" type="checkbox"/>
282785	WELL	PR	01/23/2006	GW	045-11828	N.PARACHUTE MF01C CO4 696	PR	<input checked="" type="checkbox"/>
282786	WELL	PR	07/24/2009	GW	045-11827	N. PARACHUTE MF07A-4 CO4 696	PR	<input checked="" type="checkbox"/>
284640	WELL	PR	12/01/2009	GW	045-12249	N. PARACHUTE MF06B-4 CO4 696	PR	<input checked="" type="checkbox"/>
295477	WELL	PR	03/01/2010	GW	045-15766	N. PARACHUTE MF01C-4 CO4 696	PR	<input checked="" type="checkbox"/>
295478	WELL	PR	07/14/2011	GW	045-15767	N. PARACHUTE MF13D-31 C04 69	PR	<input checked="" type="checkbox"/>
295479	WELL	PR	02/20/2010	GW	045-15768	N. PARACHUTE MF04B-3 CO4 696	PR	<input checked="" type="checkbox"/>
295480	WELL	PR	02/15/2010	GW	045-15769	N. PARACHUTE MF03C-4 CO4 696	PR	<input checked="" type="checkbox"/>
295481	WELL	PR	01/14/2010	GW	045-15770	N. PARACHUTE MF02C-4 CO4 696	PR	<input checked="" type="checkbox"/>
295482	WELL	PR	02/10/2010	GW	045-15771	N. PARACHUTE MF06A-4 CO4 696	PR	<input checked="" type="checkbox"/>
295483	WELL	PR	02/22/2010	GW	045-15772	N. PARACHUTE MF02B-4 CO4 696	PR	<input checked="" type="checkbox"/>
295487	WELL	PR	01/13/2010	GW	045-15777	N. PARACHUTE MF13C-31 C04 69	PR	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location****Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
CONTAINERS	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD	SATISFACTORY			
BATTERY	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: **800-791-7691**

Inspector Name: LONGWORTH, MIKE

Corrective Action:

**Good Housekeeping:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Equipment:**

Type: Gas Meter Run	# 19	Satisfactory/Action Required:	SATISFACTORY
Comment	Gas lift		
Corrective Action	Date:		
Type: Gas Meter Run	# 19	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action	Date:		
Type: Plunger Lift	# 19	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action	Date:		
Type: Ancillary equipment	# 3	Satisfactory/Action Required:	SATISFACTORY
Comment	Chemical containers		
Corrective Action	Date:		

**Facilities:**☐ New Tank

Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST	,

S/AR	SATISFACTORY	Comment:	
Corrective Action:		Corrective Date:	

**Paint**

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) 80 bbl \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
Comment			

**Venting:**

Yes/No NO

Comment

**Flaring:**

Type

Satisfactory/Action Required

Comment:

Corrective Action:

Correct Action

Date:

**Predrill**

Location ID: 311638

**Site Preparation:**

Lease Road Adeq.:

Pads:

Soil Stockpile:

**S/AR:**

Corrective Action:

Date:

CDP Num.:

**Form 2A COAs:****S/AR:****Comment:****CA:****Date:****Wildlife BMPs:****S/AR:****Comment:****CA:****Date:****Comment:****Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name:

Address:

Phone Number:

Cell Phone:

Operator Rep. Contact Information:

Landman Name:

Phone Number:

Date Onsite Request Received:

Date of Rule 306 Consultation:

Request LGD Attendance:

LGD Contact Information:

Name:

Phone Number:

Agreed to Attend:

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 282774

Type:

WELL

API Number: 045-11838

Status: PR

Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID:	282776	Type:	WELL	API Number:	045-11836	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	282777	Type:	WELL	API Number:	045-11835	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	282778	Type:	WELL	API Number:	045-11834	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	282779	Type:	WELL	API Number:	045-11833	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	282780	Type:	WELL	API Number:	045-11832	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	282781	Type:	WELL	API Number:	045-11831	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	282784	Type:	WELL	API Number:	045-11829	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	282785	Type:	WELL	API Number:	045-11828	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	282786	Type:	WELL	API Number:	045-11827	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	284640	Type:	WELL	API Number:	045-12249	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	295477	Type:	WELL	API Number:	045-15766	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	295478	Type:	WELL	API Number:	045-15767	Status:	PR	Insp. Status:	PR

Inspector Name: LONGWORTH, MIKE

**Producing Well**

Comment: **Producing well**

Facility ID: 295479 Type: WELL API Number: 045-15768 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Producing well**

Facility ID: 295480 Type: WELL API Number: 045-15769 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Producing well**

Facility ID: 295481 Type: WELL API Number: 045-15770 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Producing well**

Facility ID: 295482 Type: WELL API Number: 045-15771 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Producing well**

Facility ID: 295483 Type: WELL API Number: 045-15772 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Producing well**

Facility ID: 295487 Type: WELL API Number: 045-15777 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Producing well**

**Environmental**

**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

**Water Well:**

DWR Receipt Num: Owner Name: GPS : Lat Long

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_

CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_

CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_

CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_

CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_

Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_

Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Inspector Name: LONGWORTH, MIKE

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Ditches	Pass					
				MHSP	Pass	
Seeding	Pass					
Gravel	Pass					
		Compaction	Pass			
		Gravel	Pass			
Compaction	Pass					
Check Dams	Pass					
		Culverts	Pass			
		Ditches	Pass			

S/A/V: SATISFACTOR Y \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT