

Dwinell 4

Inspection# 673403092

Stained soil around wellhead.



Close up of stained soil around wellhead.

