

Photo#1:  
View North from Location Center




Photo#2:  
View South from Location Center



Photo#3:

View East from Location Center



Photo#4:

View West from Location Center






Photo#5:  
Gravel on Location



Photo#6:  
Rock Stockpile on Location





Photo#7:

Compacted Area at Location Entry

\*



Photo#8:

Appears Water is Pooling across Location, combined with Hoof activity is inhibiting Vegetation.



Photo#9:

Sediment moving off Location at West side



Photo#10:

Manure piled at NW Corner of Location.

