

Final Reclamation Inspection



Photo 1. Photo taken of operator sign at entrance of location. Need to remove sign per Rule 603.f.

Final Reclamation Inspection



Photo 2. Photo taken from entrance of location, facing North towards location. Need to reclaim access road or provide documentation (SUA) stating this road doesn't need to be reclaimed.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing West. No evidence of wellbore at location. Need to come back during the crop growing season to evaluate proper vegetative per our reclamation regulations.

Final Reclamation Inspection



Photo 4. Photo taken from center of location, facing North. No evidence of wellbore at location. Need to come back during the crop growing season to evaluate proper vegetative per our reclamation regulations.

Final Reclamation Inspection



Photo 5. Photo taken from center of location, facing East. No evidence of wellbore at location. Need to come back during the crop growing season to evaluate proper vegetative per our reclamation regulations.

Final Reclamation Inspection



Photo 6. Photo taken from center of location, facing South. No evidence of wellbore at location. Need to come back during the crop growing season to evaluate proper vegetative per our reclamation regulations.