

Interim Reclamation Inspection

3/29/2016

Operator: Atlas Resources

Location ID: 424059

Washington County, CO

NESW Section 18 T8N R43W

Aaron Trujillo

Reclamation Specialist

COGCC



Figure 1: Photo taken from well, facing north.



03.29.2016 10:24

Figure 2: Photo taken from the southwest corner of the location, facing east. Photo of interim and project areas.



Figure 3: Photo taken from the southwest corner of the location, facing north. Photo of interim and project areas.



03.29.2016 10:25

Figure 4: Photo taken from the northwest corner of the location, facing south. Photo of interim and project areas.



Figure 5: Photo taken from the northwest corner of the location, facing east. Photo of interim and project areas.



Figure 6: Photo taken from the northeast corner of the location, facing west. Photo of interim and project areas.



Figure 7: Photo taken from the northeast corner of the location, facing south. Photo of interim and project areas.



Figure 8: Photo taken from the southeast corner of the location, facing north. Photo of interim and project areas.



Figure 9: Photo taken from the southeast corner of the location, facing west. Photo of interim and project areas.