

**697-1X pad location**  
**Interim Reclamation - Revegetation**

**Page 1 of 3**

10/31/2011 grading and seeding began  
11/01/2011 grading and seeding complete

Photos taken 5/21/2014



Southern edge of pad near southwest corner



Western edge of pad



Western edge of pad



Western edge of pad



Northern edge of pad



Northern edge of pad



Top soil pile near northeast corner



Northeastern corner of pad



Reclaimed area east of pad



Eastern edge of reclaimed area east of pad





Reclaimed area east of pad



Reclaimed area east of pad



Reclaimed area east of pad



Reclaimed area east of pad, looking southwest across pad