

# Interim Location Inspection

3/29/2016

Operator: Atlas Resources

Location ID: 416083

Phillips County, CO

NESE Section 18 T8N R43W

Aaron Trujillo

Reclamation Specialist

COGCC



**Figure 1:** Photo of wellhead and sign.



**Figure 2:** Photo Taken from the northeast end of the location, facing west. Photo shows interim and project areas.



03\_29\_2016 11:11

**Figure 3:** Photo Taken from the northeast end of the location, facing south. Photo shows interim and project areas.



**Figure 4:** Photo Taken from the southeast end of the location, facing north. Photo shows interim and project areas.



**Figure 5:** Photo Taken from the southeast end of the location, facing west. Photo shows interim and project areas.



**Figure 6:** Photo Taken from the southwest end of the location, facing east. Photo shows interim and project areas.



**Figure 7:** Photo Taken from the southwest end of the location, facing north. Photo shows interim and project areas.



**Figure 8:** Photo taken from the northwest end of the location, facing south. Photo shows interim and project areas.



**Figure 9:** Photo taken from the northwest end of the location, facing east. Photo shows interim and project areas.



**Figure 10:** Photo of disturbance quadrat #1. Transect conducted on the northeast end of the interim area.




**Figure 11:** Photo of disturbance quadrat #2. Transect conducted on the northwest end of the interim area.



**Figure 12:** Photo of disturbance quadrat #3. Transect conducted on the southern end of the interim area.



**Figure 13:** Photo of reference quadrat #1. Transect conducted south of the location.



**Figure 14:** Photo of reference quadrat #2. Transect conducted northeast of the location.