

**596-34D pad location**  
**Interim Reclamation - revegetation**

11/01/2011 grading and seeding began  
11/02/2011 grading and seeding complete

Photos taken 5/21/2014



South-facing fill slope for access road




Southeast corner of pad



Southern edge of pad



Top soil pile



Top soil pile



Top soil pile



Southern edge of pad



Southwest corner of pad



Southwest corner of pad



Western edge of pad



Western edge of pad



Looking northeast across pad



Eastern edge of pad



North-facing fill slope for access road