

**FORM INSP**  
Rev 05/11

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
03/31/2016  
Document Number:  
673901263  
Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

|                     |               |               |                      |                          |             |
|---------------------|---------------|---------------|----------------------|--------------------------|-------------|
| Location Identifier | Facility ID   | Loc ID        | Inspector Name:      | On-Site Inspection       | 2A Doc Num: |
|                     | <u>243270</u> | <u>319319</u> | <u>MONTOYA, JOHN</u> | <input type="checkbox"/> |             |

**Operator Information:**

OGCC Operator Number: 10548  
Name of Operator: HRM RESOURCES II LLC  
Address: 410 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name  | Phone        | Email                   | Comment         |
|---------------|--------------|-------------------------|-----------------|
| Pape, Terry   | 303-893-6621 | tpape@hrmres.com        | All Inspections |
| OLSON, JUSTIN | 030-910-4717 | justin.olson@hrmres.com | engineering     |

**Compliance Summary:**

QtrQtr: SENW Sec: 34 Twp: 1N Range: 64W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 09/24/2015 | 671105277 | PR         | SI          | <b>ACTION REQUIRED</b>        |          |                | No              |
| 01/06/2009 | 200203997 | PR         | PR          | SATISFACTORY                  |          |                | No              |
| 02/04/2002 | 200024087 | PR         | PR          | SATISFACTORY                  |          | <b>Fail</b>    | Yes             |
| 05/11/1998 | 500166517 | PR         | PR          |                               |          |                |                 |
| 06/26/1996 | 500166516 | PR         | PR          |                               |          |                |                 |
| 08/11/1994 | 500166515 |            | PR          |                               |          |                |                 |

**Inspector Comment:**

**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name          | Insp Status                            |
|-------------|------|--------|-------------|------------|-----------|------------------------|--|
| 101174      | PIT  |        | 09/23/1999  |            | -         | BBR ABBOTT FARMS 13-34 | <input type="checkbox"/>               |
| 243270      | WELL | PR     | 05/01/2014  | GW         | 123-11061 | BBR ABBOTT FARMS 22-34 | SI <input checked="" type="checkbox"/> |

**Equipment:**

Location Inventory

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

|                    |                              |         |                   |      |
|--------------------|------------------------------|---------|-------------------|------|
| <b>Lease Road:</b> |                              |         |                   |      |
| Type               | Satisfactory/Action Required | comment | Corrective Action | Date |
| Access             | SATISFACTORY                 |         |                   |      |

|                      |                              |         |                   |         |
|----------------------|------------------------------|---------|-------------------|---------|
| <b>Signs/Marker:</b> |                              |         |                   |         |
| Type                 | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD             | SATISFACTORY                 |         |                   |         |

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

|                           |                              |         |                   |         |
|---------------------------|------------------------------|---------|-------------------|---------|
| <b>Good Housekeeping:</b> |                              |         |                   |         |
| Type                      | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|                           |                              |         |                   |         |

|  |      |        |                   |         |
|--|------|--------|-------------------|---------|
| <b>Spills:</b>   |      |        |                   |         |
| Type   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

|                  |                              |         |                   |         |
|------------------|------------------------------|---------|-------------------|---------|
| <b>Fencing/:</b> |                              |         |                   |         |
| Type             | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|                  |                              |         |                   |         |

|                    |     |  |  |       |
|--------------------|-----|--|--|-------|
| <b>Equipment:</b>  |     |  |  |       |
| Type: Plunger Lift | # 1 | Satisfactory/Action Required: SATISFACTORY |  |       |
| Comment            |     |  |  |       |
| Corrective Action  |     |  |  | Date: |

|                 |  |  |  |  |
|-----------------|--|--|--|--|
| <b>Venting:</b> |  |  |  |  |
| Yes/No          |  |  |  |  |
| Comment         |  |  |  |  |

|                    |                              |  |  |                      |
|--------------------|------------------------------|--|--|----------------------|
| <b>Flaring:</b>    |                              |  |  |                      |
| Type               | Satisfactory/Action Required |  |  |                      |
| Comment:           |                              |  |  |                      |
| Corrective Action: |                              |  |  | Correct Action Date: |

**Predrill**

Location ID: 243270

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

S/AR: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 243270 Type: WELL API Number: 123-11061 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

S/A/V: \_\_\_\_\_ CA Date: \_\_\_\_\_

CA: \_\_\_\_\_

Comment: \_\_\_\_\_

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:** \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_  
 DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_  
 Land Use: \_\_\_\_\_  
 Comment: \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_  
 CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_  
 CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_  
 CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_  
 CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_  
 1003 f. Weeds Noxious weeds? \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**  
 Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_  
 Final Land Use: \_\_\_\_\_  
 Reminder: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_  
 Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_  
 Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_  
 Gravel removed \_\_\_\_\_  
 Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_  
 Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_  
 Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_  
 Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_  
 Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

S/A/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 CA: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment  | User     | Date       |
|--|----------|------------|
| INTERMITTER CONTROLLER ON WELLHEAD, DOCUMENT # 6711025277, DATED 9/24/15, UNUSED PIPE PICKED UP BERMS REPAIRED, SOILED DIRT CLEANED UP IN SEP HOUSES | montoyaj | 03/31/2016 |