

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/29/2016

Document Number:

673712982

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	209361	322151	Sherman, Susan	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Ingve, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
Espinosa, Bill	(303) 829-4982	billespinosa30@yahoo.com	
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	All Inspections

Compliance Summary:QtrQtr: NWNW Sec: 24 Twp: 6S Range: 63W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/19/2013	673700420	PR	PR	ALLEGED VIOLATION			Yes
03/22/2012	664000423	PR	SI	ACTION REQUIRED	P		No
07/28/2010	200264787	PR	SI	SATISFACTORY			No
01/24/2006	200083504	PR	PR	SATISFACTORY		Pass	No
04/16/2004	200053423	ID	TA	ACTION REQUIRED		Fail	Yes
04/27/2000	895787	PR	PR	ACTION REQUIRED		Fail	Yes
12/17/1999	894242	ID	SI	ACTION REQUIRED		Fail	Yes
12/01/1999	882734	ES	PR	ACTION REQUIRED		Fail	Yes
12/01/1999	882761	ES	PR	ACTION REQUIRED		Fail	Yes
11/17/1999	894213	ES	SI	ACTION REQUIRED		Fail	Yes
11/08/1999	882763	ES	PR	ACTION REQUIRED		Fail	Yes
11/08/1999	882760	ES	PR	ACTION REQUIRED		Fail	Yes
11/01/1999	882759	ES	PR	ACTION REQUIRED		Fail	
11/01/1999	882762	ES	PR	ACTION REQUIRED		Fail	Yes
10/26/1999	882732	ES	PR	ACTION REQUIRED		Fail	Yes
10/26/1999	882758	ES	PR	ACTION REQUIRED		Fail	Yes
10/20/1999	882757	ES	PR	ACTION REQUIRED		Fail	Yes
10/20/1999	882733	ES	PR	ACTION REQUIRED		Fail	Yes
09/17/1999	845055	ES	UN	ACTION REQUIRED			

Inspector Name: Sherman, Susan

09/16/1999	200014274	ES	PR	ACTION REQUIRED		Fail	Yes
07/22/1999	882756	ES	PR	ACTION REQUIRED		Fail	Yes
07/19/1999	882755	ES	PR	ACTION REQUIRED		Fail	Yes
07/02/1999	500141332	CO	SI			Fail	Yes
11/06/1997	500141331	PR	PR			Fail	Yes

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
119949	PIT	CL	02/29/2000		-	MORRIS 24-4	CL	<input type="checkbox"/>
209361	WELL	PR	03/06/2007	OW	039-06265	MORRIS 24-4	PR	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD	SATISFACTORY			
BATTERY	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Inspector Name: Sherman, Susan

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:				
Type: Gas Meter Run	# 1	Satisfactory/Action Required:		
Comment	door on ground next to meter (see attached photo)			
Corrective Action				Date:

Venting:	
Yes/No	
Comment	

Flaring:			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 209361

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:**S/AR:** SATISFACTORY**Comment:** No COAs.**CA:** _____**Date:** _____**Wildlife BMPs:****S/AR:** _____**Comment:** _____**CA:** _____**Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 209361

Type: WELL

API Number: 039-06265

Status: PR

Insp. Status: PR

Producing Well

Comment: PR. Dec 2015 reported to COGCC database.

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____

Date: _____

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: pasture, well is ~120' west of creek

1003a. Waste and Debris removed? Pass

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass

CM _____

CA _____ CA Date _____

Guy line anchors marked? Pass

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Inspector Name: Sherman, Susan

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction		Compaction				

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment: creek running and deadman in water (see attached photo)

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Corrective actions from inspeciton #673700420 completed.	ShermaSe	04/01/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673713028	Renegade Morris 24-4	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3823022