

## Final Reclamation Inspection



**Photo 1.** Photo taken of produced water pit west of 300 bbl tank. Pit needs to be backfilled and reclaimed per Rule 1004. Spread and infestation of a Colorado List B noxious weed (Bull thistle- *Cirsium vulgare*) exists throughout the location, along the lease road, and spreading onto adjacent lands needs to be controlled per Rule 1004.

## Final Reclamation Inspection



**Photo 2.** Photo taken of bull thistle infestation west of produced water, facing East towards 300 bbl tank. Need to control noxious weeds per Rule 1004.

## Final Reclamation Inspection



**Photo 3.** Photo taken of 300 bbl tank with pooled water and hydrocarbon odors. Need to remove all surface equipment within three months of plugging a well, backfill and reclaim area per Rule 1004.

## Final Reclamation Inspection



**Photo 4.** Photo taken east of 300 bbl tank of possible workover/plugging pit. Need to backfill and reclaim per Rule 1004.

## Final Reclamation Inspection



**Photo 5.** Photo taken of 2-phase separator, north of the 300 bbl tank. Need to remove all surface equipment within three months of plugging a well per Rule 1004.

## Final Reclamation Inspection



**Photo 6.** Photo taken northwest of produced water pit, facing North along lease road. All access roads to plugged and abandoned wells shall be closed, graded, and recontoured per Rule 1004.

## Final Reclamation Inspection



**Photo 7.** Photo taken from northeast corner of lease road, facing North. Need to control noxious weeds per Rule 1004.

## Final Reclamation Inspection



**Photo 8.** Photo taken from northeast corner of lease road, facing West. Under the Colorado Noxious Weed Act, noxious weeds must be prevented from spreading to surrounding lands. Bull thistle was observed throughout adjacent lands.