

Final Reclamation Inspection



Photo 1. Photo taken from east of location, facing West. Gravel not removed and location does not reflect reference area vegetative cover per Rule 1004.

Final Reclamation Inspection



Photo 2. Photo taken from south of location, facing North. Gravel not removed and location does not reflect reference area vegetative cover per Rule 1004.

Final Reclamation Inspection



Photo 3. Photo taken from west of location, facing East. Gravel not removed and location does not reflect reference area vegetative cover per Rule 1004.

Final Reclamation Inspection



Photo 4. Photo taken from north of location, facing South. Gravel not removed and location does not reflect reference area vegetative cover per Rule 1004.

Final Reclamation Inspection



Photo 5. Photo taken from center of location. Gravel not removed and location does not reflect reference area vegetative cover per Rule 1004.

Final Reclamation Inspection- Reference Area



Photo 6. Photo taken from east of location, facing East. Reference area illustrates uniform vegetative cover.

Final Reclamation Inspection



Photo 7. Photo taken from east of location, facing East. Reference area illustrates uniform vegetative cover.