



Photo#1: Looking North at Location from Ridge approx. ¼ Mile to South.

Photo#2:  
View North over Location Center



Photo#3:  
View South over Location Center



Photo#4:  
View East over Location Center



Photo#5:  
View West over Location Center



Photo#6:  
Trash & Rock Stockpile




Photo#7:  
Emerging Vegetation, bones scattered over Loc.



Photo#8:  
Cut Slope at SE end of Loc.




Photo#9:  
Reference Area Vegetation



Photo#5:  
Access Road Exiting Location.

Photo#6:  
View up Access Road into Location.





Photo#10: View to East of Pad & Cut Slope.

March 5, 2016

Inspection Photos TRW P&A 045-06461