



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward.





Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward. Revegetation is progressing here and is largely comprised of crested wheatgrass (*Agropyron cristatum*), intermediate wheatgrass (*Thinopyron intermedium*), and western wheatgrass (*Pascopyrum smithii*).



Photo 4. View of an approximately 50 foot long and 25 feet wide area in the western portion of the interim reclamation area that needs revegetation.





Photo 5. View of area in northwestern portion of the project area where wattles are no longer functioning.



Photo 6. View of the northern portion of the project area from the northwestern corner facing eastward. Horsetrailer, sheds, vehicle, and other debris are being stored on the well pad.