

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/06/2016

Document Number:

685300292

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	213816	325012	St John, William (Cal)	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: PO BOX 4289City: FARMINGTON State: NM Zip: 87499

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
McDaniel, Heather	505-326-5507	hearther.d.mcdaniel@conocophillips.com	SW Inspection Reports
Busse, Dollie	505-324-6104	dollie.l.bussie@conocophillips.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	COGCC

Compliance Summary:QtrQtr: SENE Sec: 13 Twp: 32N Range: 10W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/24/2014	674600279	PR	PR	SATISFACTORY	P		No
10/18/2006	200105964	PR	PR	SATISFACTORY		Pass	No
09/19/2005	200079614	PR	PR	SATISFACTORY		Pass	No
01/07/2004	200052094	PR	PR	SATISFACTORY		Pass	No
11/14/2002	200032849	PR	PR	SATISFACTORY		Pass	No
05/18/2001	200018807	PR	PR	SATISFACTORY		Pass	No
03/24/1999	500146311	PR	PR			Pass	No
06/05/1997	500146310	BH	PR			Pass	No
01/03/1996	500146309	PR	PR			Pass	No
08/15/1994	500146308	PR	PR			Pass	No

Inspector Comment:

This report contains corrective actions. See Lease Road, Signs/Markers, and Facilities for additional comments. See link at end of report for path to downloadable pictures.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
213816	WELL	PR	03/05/1958	GW	067-05082	SEVER 1	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Inspector Name: St John, William (Cal)

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY	Access road in need of maintenance.		

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	ACTION REQUIRED	No signage on open top tank.	Install sign to comply with rule 210.	06/03/2016

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
OTHER	SATISFACTORY	Post and Hog Wire - Open Top Produced Water Tank		
OTHER	SATISFACTORY	Post and Hog Wire - Produced Water Tank		

Equipment:				
Type: Ancillary equipment	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment	Wellhead			
Corrective Action				Date:
Type: Vertical Heated Separator	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment				
Corrective Action				Date:

Type: Bird Protectors	# 2	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:
Type: Dehydrator	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:
Type: Other	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment Domestic Tap			
Corrective Action			Date:
Type: Gas Meter Run	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:
Type: Flow Line	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:

Facilities:
☐ New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1		Open Top	,
S/AR	SATISFACTORY		Comment: No signage on tank or fencing.	
Corrective Action:			Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Corrective Action	Repair or install berms or other secondary containment devices per Rule 604.c. (2).G.			Corrective Date 04/27/2016
Comment	Berms are mud cracked and beaten down by weather, nearly flat in places, capacity and integrity appear inadequate.			

Facilities:
☐ New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL	,
S/AR	SATISFACTORY		Comment:	
Corrective Action:			Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) 60 BBLS

Other (Type) _____

Inspector Name: St John, William (Cal)

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					

Venting:	
Yes/No	NO
Comment	

Flaring:			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 213816

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:S/AR: _____ **Comment:** _____

CA: _____

Date: _____**Wildlife BMPs:**S/AR: _____ **Comment:** _____

CA: _____

Date: _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 213816

Type: WELL

API Number: 067-05082

Status: PR

Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Witness Braden Head Monitoring Test. Initial pressure reading 1 PSI. Final pressure reading 0 PSI. Instantaneous reading 0 PSI. Production Casing 357 PSI. Tubing 357 PSI

CA: _____

CA Date: _____

Environmental**Spills/Releases:**

Inspector Name: St John, William (Cal)

Type of Spill: _____	Description: _____	Estimated Spill Volume: _____
Comment: _____		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	

Water Well:		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	_____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:	
Date Interim Reclamation Started: _____	Date Interim Reclamation Completed: _____
Land Use: _____	
Comment: _____	
1003a. Waste and Debris removed? _____	
CM _____	
CA _____	CA Date _____
Unused or unneeded equipment onsite? _____	
CM _____	
CA _____	CA Date _____
Pit, cellars, rat holes and other bores closed? _____	
CM _____	
CA _____	CA Date _____
Guy line anchors marked? _____	
CM _____	
CA _____	CA Date _____
1003b. Area no longer in use? _____	Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____	
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____	
Production areas have been stabilized? _____	Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION	
<u>Cropland</u>	

Inspector Name: St John, William (Cal)

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Gravel	Pass	Ditches	Pass			
Berms	Pass	Compaction	Pass			

S/A/V: SATISFACTOR

Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685300309	Tank with no signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3830041
685300310	Weathered Berms 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3830042
685300311	Weathered Berms 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3830043