



**photo 1:** Facing southeast at the beginning of the former access road.



**photo 2:** Area along the former access road which does not appear to have vegetation establishment.



**photo 3:** Center of the location facing north.



**photo 4:** Center of the location facing west.



**photo 5:** Center of the location facing south.



**photo 6:** Center of the location facing east.



**photo 7:** View of groundcover at center of the location.



**photo 8:** Weed debris noticed throughout the location (Kochia, Russian thistle).



**photo 9:** Surrounding field north of the location. Facing north at Lat/Long:37.01238,-102.26977.



**photo 10:** What appears to be Sand dropseed established in the surrounding field.