

Interim Reclamation Inspection

4/13/2016

Operator: Caerus Washco LLC

Location ID: 421744

Weld County, CO

SWSW Section 36 T7N R61W

Aaron Trujillo

Reclamation Specialist

COGCC



04.13.2016 12:46

Figure 1: Photo taken from the south end of the location, facing north. Photo of sign at tank battery.



04.13.2016 12:46

Figure 2: Photo taken from the southeast corner of the location, facing north. Photo shows project area.



Figure 3: Photo taken from the southeast corner of the location, facing north. Photo shows interim and project areas.



Figure 4: Photo taken from the northeast corner of the location, facing west. Photo shows interim and project areas.



Figure 5: Photo taken from the southeast corner of the location, facing south. Photo shows interim and project areas.



Figure 6: Photo taken at well.



Figure 7: Photo taken from the northwest corner of the location, facing southeast. Photo shows interim and project areas.



Figure 8: Photo taken from the northwest corner of the location, facing south. Photo shows interim and project areas.



Figure 9: Photo taken from the southwest corner of the location, facing north. Photo shows interim and project areas.



Figure 10: Photo taken from the southwest corner of the location, facing east. Photo shows project area.