

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/19/2016

Document Number:

666802071

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	415718	311645	Murray, Richard	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Compliance Summary:**QtrQtr: NESW Sec: 8 Twp: 7S Range: 93W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/08/2011	661400037	PR	PR	SATISFACTORY			No

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
278652	WELL	PR	02/16/2006	GW	045-10908	GMR 8-11 (K8W)	PR	<input checked="" type="checkbox"/>
284219	WELL	PR	04/21/2011	GW	045-12101	GMR 8-6 (K8W)	PR	<input checked="" type="checkbox"/>
415712	WELL	PR	12/09/2010	GW	045-19143	GMR 8-6A2 (K8W)	PR	<input checked="" type="checkbox"/>
415713	WELL	PR	10/10/2011	GW	045-19144	GMR 8-12B (K8W)	PR	<input checked="" type="checkbox"/>
415716	WELL	PR	11/18/2010	GW	045-19145	GMR 8-5B1 (K8W)	PR	<input checked="" type="checkbox"/>
415717	WELL	PR	10/10/2011	GW	045-19146	GMR 8-11C (K8W)	PR	<input checked="" type="checkbox"/>
415718	WELL	PR	12/14/2010	GW	045-19147	GMR 8-6A1 (K8W)	PR	<input checked="" type="checkbox"/>
415719	WELL	PR	10/10/2011	GW	045-19148	GMR 8-12C2 (K8W)	PR	<input checked="" type="checkbox"/>
415720	WELL	PR	10/10/2011	GW	045-19149	GMR 8-5C1 (K8W)	PR	<input checked="" type="checkbox"/>
415722	WELL	PR	11/29/2010	GW	045-19150	GMR 8-6D (K8W)	PR	<input checked="" type="checkbox"/>

Inspector Name: Murray, Richard

415723	WELL	PR	07/07/2011	GW	045-19151	GMR 8-11A2 (K8W)	PR	<input checked="" type="checkbox"/>
415724	WELL	PR	08/04/2011	GW	045-19152	GMR 8-11A1 (K8W)	PR	<input checked="" type="checkbox"/>
415725	WELL	PR	11/15/2010	GW	045-19153	GMR 8-5B2 (K8W)	PR	<input checked="" type="checkbox"/>
415728	WELL	PR	10/10/2011	GW	045-19154	GMR 8-12C1 (K8W)	PR	<input checked="" type="checkbox"/>
415729	WELL	PR	11/11/2010	GW	045-19155	GMR 8-5D (K8W)	PR	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>15</u>	Production Pits: _____
Condensate Tanks: <u>8</u>	Water Tanks: _____	Separators: <u>15</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: <u>1</u>
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: <u>1</u>	Fuel Tanks: _____

**Location****Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY	AIRS ID 045-1373-001		

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Equipment:**

Type: Emission Control Device	# 1	Satisfactory/Action Required: SATISFACTORY
Comment		

Inspector Name: Murray, Richard

Corrective Action		Date:
Type: Gas Meter Run	# 1	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action		Date:
Type: Vertical Heated Separator	# 15	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action		Date:
Type: Plunger Lift	# 15	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action		Date:

**Facilities:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
CONDENSATE	3	400 BBLS	HEATED STEEL AST	39.458840,-107.800314

S/AR	SATISFACTORY	Comment:
Corrective Action:		Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date
Comment		

**Facilities:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
CONDENSATE	5	400 BBLS	STEEL AST	39.458832,-107.800832

S/AR	SATISFACTORY	Comment:
Corrective Action:		Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date
Comment		

**Venting:**

Yes/No NO

Comment

**Flaring:**

Type	Satisfactory/Action Required		
Comment:			
Corrective Action:		Correct Action Date:	

**Predrill**

Location ID: 415718

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

S/AR: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 278652 Type: WELL API Number: 045-10908 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Facility ID: 284219	Type: WELL	API Number: 045-12101	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Facility ID: 415712	Type: WELL	API Number: 045-19143	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Facility ID: 415713	Type: WELL	API Number: 045-19144	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Facility ID: 415716	Type: WELL	API Number: 045-19145	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Facility ID: 415717	Type: WELL	API Number: 045-19146	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Facility ID: 415718	Type: WELL	API Number: 045-19147	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Facility ID: 415719	Type: WELL	API Number: 045-19148	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Facility ID: 415720	Type: WELL	API Number: 045-19149	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Facility ID: 415722	Type: WELL	API Number: 045-19150	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Facility ID: 415723	Type: WELL	API Number: 045-19151	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Facility ID: 415724	Type: WELL	API Number: 045-19152	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Facility ID: 415725	Type: WELL	API Number: 045-19153	Status: PR	Insp. Status: PR

Inspector Name: Murray, Richard

**Producing Well**

Comment: **Plunger lift**

Facility ID: 415728 Type: WELL API Number: 045-19154 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 415729 Type: WELL API Number: 045-19155 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): Y

Comment: \_\_\_\_\_

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Retention Ponds	Pass					
		Ditches	Pass			
Gravel	Pass					

Inspector Name: Murray, Richard

		Culverts	Pass			
Berms	Pass					
Rip Rap	Pass					
		Gravel	Pass			

S/A/V: SATISFACTOR  
Y

Corrective Date: \_\_\_\_\_

Comment:

CA:

**Pits:** ☒ NO SURFACE INDICATION OF PIT

### **Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666802071	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3837119">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3837119</a>