

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/20/2016

Document Number:

666802076

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	211398	334838	Murray, Richard	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Compliance Summary:QtrQtr: NWNE Sec: 7 Twp: 7S Range: 92W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/17/2006	200105493	PR	PR	SATISFACTORY		Pass	No
07/16/2002	200038462	PR	PR	SATISFACTORY		Pass	No
11/05/1998	500143024	PR	PR			Pass	No
12/09/1997	500143023	CO	PR				

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
211398	WELL	PR	06/01/1997	GW	045-07158	KRK 7-2	PR	<input checked="" type="checkbox"/>
262826	WELL	PR	08/28/2002	GW	045-08052	KRK 7-3B (B7)	PR	<input checked="" type="checkbox"/>
262828	WELL	PR	08/09/2002	GW	045-08054	K R K 7-2B (B7)	PR	<input checked="" type="checkbox"/>
262829	WELL	PR	08/09/2002	GW	045-08055	K R K 7-1B (B7)	PR	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Inspector Name: Murray, Richard

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
STORAGE OF SUPL	SATISFACTORY	2 concrete bankets		
UNUSED EQUIPMENT	SATISFACTORY	Max-Heat trailer		

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type: Gas Meter Run	# 2	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date: _____
Type: Horizontal Heated Separator	# 4	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date: _____

Facilities:

☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	0			,

Inspector Name: Murray, Richard

S/AR	SATISFACTORY	Comment:			
Corrective Action:					Corrective Date:
<u>Paint</u>					
Condition					
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Corrective Action					Corrective Date
Comment					
Facilities: <input type="checkbox"/> New Tank Tank ID: _____					
Contents	#	Capacity	Type	SE GPS	
METHANOL	1	1000 GAL	STEEL AST	,	
S/AR	SATISFACTORY	Comment:	Centralized battery		
Corrective Action:					Corrective Date:
<u>Paint</u>					
Condition		Adequate			
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Corrective Action					Corrective Date
Comment					
Facilities: <input type="checkbox"/> New Tank Tank ID: _____					
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST	39.466728,-107.706417	
S/AR	SATISFACTORY	Comment:			
Corrective Action:					Corrective Date:
<u>Paint</u>					
Condition		Adequate			
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action					Corrective Date

Inspector Name: Murray, Richard

Comment	
---------	--

Venting:

Yes/No	NO
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 211398

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

--

Summary of Operator Response to Landowner Issues:

--

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

--

Facility

Facility ID: 211398 Type: WELL API Number: 045-07158 Status: PR Insp. Status: PR

Inspector Name: Murray, Richard

Producing Well

Comment: **Plunger lift**

Facility ID: 262826 Type: WELL API Number: 045-08052 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 262828 Type: WELL API Number: 045-08054 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 262829 Type: WELL API Number: 045-08055 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS : Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB): N

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Waste and Debris removed? Pass

CM

CA CA Date

Unused or unneeded equipment onsite? Pass

CM

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Inspector Name: Murray, Richard

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
		Ditches	Pass			
Ditches	Pass					
		Culverts	Pass			
		Gravel	Pass			

S/A/V: SATISFACTOR
Y _____

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT