

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401032769

Date Received:

04/20/2016

SPILL/RELEASE REPORT (INITIAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

Spill report taken by:

Spencer, Stan

Spill/Release Point ID:

445567

OPERATOR INFORMATION

Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLC	Operator No: 96850	Phone Numbers
Address: PO BOX 370		Phone: (970) 6832295
City: PARACHUTE State: CO Zip: 81635		Mobile: (970) 5890743
Contact Person: Karolina Blaney		Email: karolina.blaney@wpxenergy.com

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401032769

Initial Report Date: 04/20/2016 Date of Discovery: 04/20/2016 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SWSE SEC 17 TWP 6S RNG 94W MERIDIAN 6

Latitude: 39.520065 Longitude: -107.909107

Municipality (if within municipal boundaries): County: GARFIELD

Reference Location:

Facility Type: WELL PAD Facility/Location ID No 335271
 No Existing Facility or Location ID No.
 Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=5 and <100

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

Land Use:

Current Land Use: NON-CROP LAND Other(Specify):

Weather Condition: warm, 55F, cloudy

Surface Owner: FEDERAL Other(Specify):

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State Residence/Occupied Structure Livestock Public Byway Surface Water Supply Area

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

The spill was caused by corrosion of a produced water tank. Produced water leaked out of the tank into the dirt SPCC containment; the soil impacts are 2-3" deep. The estimated volume of spilled water is 10 bbls; all of the free standing fluids were recovered with a vac truck. In accordance with the COGCC Rules 910.b.(3) C, D, and E, WPX would like to ask for COGCC permission to analyze the confirmation sample(s) for the abbreviated list of the Table 910-1 analytes which would include TPH, BTEX, PAHs, EC, SAR, and pH and the background samples would be analyzed for EC, SAR, and pH. The samples would not be analyzed for metals.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
4/20/2016	COGCC	Stan Spencer	970-987-2497	Initial Form 19
4/20/2016	County	Kirby Wynn	970-625-5905	Email
4/20/2016	Fire Department	David Blair	970-285-9119	Email
4/20/2016	BLM	Jim Byers	970-876-9056	Phone conversation & Email

OPERATOR COMMENTS:

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Karolina Blaney
 Title: Environmental Specialist Date: 04/20/2016 Email: karolina.blaney@wpxenergy.com

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

401032769	FORM 19 SUBMITTED
-----------	-------------------

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

Environmental	Revised analytical suite is approved. Assess nature and extent of contamination with confirmation soil samples. Remediate to Table 910-1 standards and provide documentation in a either a Supplemental F-19 if cleaned up immediately or F-27 if extended remediation is required.	4/22/2016 9:34:25 AM
---------------	---	-------------------------

Total: 1 comment(s)