

Final Reclamation Inspection

4/19/2016

Operator: Vista Operating

Location ID: 317420

Washington County, CO

SESW Section 31 T2S R50W

Aaron Trujillo

Reclamation Specialist

COGCC



Figure 1: Photo of GPS confirming location.



Figure 2: Photo taken from the west end of the pit location, facing east. Pit located north of well. Area appears to have had work done recently. Straw appears to have been spread over areas of the pit, not properly crimped. Unable to find evidence location has been seeded.



Bare Area
Figures 7 & 8

04.19.2016 14:11

Figure 3: Photo taken from the north end of the location, facing southwest. Area appears to have had work done recently. Straw appears to have been spread over areas of the pit, not properly crimped. Unable to find evidence location has been seeded. Bare area identified in figures 7 and 8 top right of photo.



Figure 4: Photo taken from the north end of the location, facing south. Area appears to have had work done recently. Straw appears to have been spread over areas of the pit, not properly crimped. Unable to find evidence location has been seeded.



Figure 5: Photo taken from the north end of the location, facing southeast. Area appears to have had work done recently. Straw appears to have been spread over areas of the pit, not properly crimped. Unable to find evidence location has been seeded.



Figure 6: Photo taken of access road. Photo shows straw spread over access road.



Figure 7: Photo taken from the west end of the location (identified in figure 3), facing southwest. Photo shows large area on location that remains unvegetated. Unlike pit, no work appears to have recently been done over this area. Area will need to be reclaimed.



Figure 8: Photo taken from the west end of the location (identified in figure 3), facing southeast. Photo shows large area on location that remains unvegetated. Unlike pit, no work appears to have recently been done over this area. Area will need to be reclaimed.