



photo 1: Imagery of offsite pit which has been closed and reclaimed.



photo 2: Facing northwest at the former pit location, which has been closed and reclaimed.



photo 3: Facing west at the pit area where reclamation has recently been performed.



photo 4: Facing north at the pit area where reclamation has recently been performed.



photo 5: Facing south at the pit area where reclamation has recently been performed.



photo 6: Facing east at the pit area where reclamation has recently been performed.