

**Bulldog 5-14H-789**

Inspection# 673403147

Rills coming onto location  
behind tank battery.



No interim reclamation  
apparent.



No interim reclamation  
apparent.



No interim reclamation  
apparent.

