

# Final Reclamation Inspection

4/19/2016

Operator: Forestar Group inc

Location ID: 395653

Morgan County, CO

SWNE Section 6 T1N R56W

Aaron Trujillo

Reclamation Specialist

COGCC



Google earth

**Figure 1:** 2013 (most current) aerial imagery of location. Image is to provide overview of location. Location is approximately 4.5 acres in size.



**Figure 2:** Photo taken from the northwest corner of the location, facing east. Photo shows vegetation on the location.



**Figure 3:** Photo taken from the northwest corner of the location, facing south. Photo shows vegetation on the location.



Image USDA Farm Service Agency

Google earth

**Figure 4:** 2005 aerial imagery of location. Image shows where production facilities and pit's location within the production area. Please note pit is found in the southwest corner of the location.



**Figure 5:** Photo taken on the west end of the location, facing south. Photo shows unvegetated areas on around the former pit location that appear to have stained soil.



**Figure 6:** Photo taken on the west end of the location. Photo shows unvegetated areas on around the former pit location that appear to have stained soil. 6' measuring stick for reference.



**Figure 7:** Photo taken on the west end of the location, facing south. Photo shows unvegetated areas on the former pit location that appear to have stained soil. 6' measuring stick for reference. Note inspector disturbed soil to view sub-surface.



**Figure 8:** Photo taken on the southwest end of the location, facing west. Photo shows unvegetated areas on the former pit location. Would be the southwest corner of pit. 3.5'x2.5' measuring stick for reference.



**Figure 9:** Photo taken on the southwest end of the location, facing west. Photo shows unvegetated areas on the former pit location.



**Figure 10:** Photo taken from the southern end of the location (east end of the former pit location), facing west. Photo shows unvegetated areas on the former pit location that appear to have stained soil



**Figure 11:** Photo taken from the southern end of the location (east end of the former pit location), photo shows stained soil. 3.5'x2.5' measuring stick for reference.



**Figure 12:** Photo taken from the southeast corner of the location, facing west. Photo shows vegetation on the location.



**Figure 13:** Photo taken from the southeast corner of the location, facing north. Photo shows vegetation on the location.



**Figure 14:** Photo taken from the northeast corner of the location, facing south. Photo shows vegetation on the location.



**Figure 15:** Photo taken from the northeast corner of the location, facing northwest. Photo shows vegetation on the location.



**Figure 16:** Photo taken from the south-central portion of the project area, facing northwest. Photo shows equipment and trash debris piled and left on location.



**Figure 17:** Photo taken from the south-central portion of the project area. Photo shows equipment and trash debris piled and left on location.



**Figure 18:** Photo taken from the south-central portion of the project area. Photo shows un vegetated area on the location with what appears to be a hard substance (likely concrete) remaining on location. 3.5'x2.5' measuring stick for reference.



**Figure 19:** Photo taken from the east end of the project area, facing north. Photo shows anchor equipment have not been removed.



**Figure 20:** Photo taken from the north end of the project area facing south. Photo shows an area approximately 125' x 63' in size of the project location that remains un-reclaimed.



**Figure 21:** Photo taken on the northwest portion of the unvegetated project area (see figure 20), facing west. Photo shows areas with stained soil. Area appears to be near where the tank batteries were once located.



**Figure 22:** Photo taken on the northwest portion of the unvegetated project area (see figure 19). Photo shows areas with stained soil. Area appears to be near where the tank batteries were once located. 3.5'x2.5' measuring stick for reference.