

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/28/2016

Document Number:

674702653

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	383329	383329	LONGWORTH, MIKE	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 96850Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, WPX	970-263-2716	COGCCInspectionReports@wpxenergy.com	WPX Inspection Mail Box

**Compliance Summary:**QtrQtr: NWNW Sec: 36 Twp: 6S Range: 95W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/22/2015	674701961			SATISFACTORY			No
03/20/2015	674701115			SATISFACTORY			No
08/25/2014	674700254			SATISFACTORY			No

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
301762	WELL	PR	05/31/2010	GW	045-18263	MAHAFFEY PA 414-25	PR	<input checked="" type="checkbox"/>
301763	WELL	PR	05/31/2010	GW	045-18264	MAHAFFEY PA 314-25	PR	<input checked="" type="checkbox"/>
301764	WELL	PR	05/31/2010	GW	045-18265	MAHAFFEY PA 14-25	PR	<input checked="" type="checkbox"/>
301765	WELL	PR	02/16/2011	GW	045-18266	MAHAFFEY PA 524-25	PR	<input checked="" type="checkbox"/>
301766	WELL	PR	07/31/2010	GW	045-18267	MAHAFFEY PA 424-25	PR	<input checked="" type="checkbox"/>
301767	WELL	PR	05/31/2010	GW	045-18268	MAHAFFEY PA 324-25	PR	<input checked="" type="checkbox"/>
301768	WELL	PR	05/31/2010	GW	045-18269	MAHAFFEY PA 11-36	PR	<input checked="" type="checkbox"/>
301769	WELL	PR	05/31/2010	GW	045-18270	MAHAFFEY PA 311-36	PR	<input checked="" type="checkbox"/>
301770	WELL	PR	05/31/2010	GW	045-18271	MAHAFFEY PA 411-36	PR	<input checked="" type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

301771	WELL	PR	05/31/2010	GW	045-18272	MAHAFFEY PA 12-36	PR	✕
301772	WELL	PR	05/31/2010	GW	045-18273	MAHAFFEY PA 312-36	PR	✕
301773	WELL	PR	01/01/2012	GW	045-18274	MAHAFFEY PA 21-36	PR	✕
301774	WELL	PR	05/31/2010	GW	045-18275	MAHAFFEY PA 321-36	PR	✕
301775	WELL	PR	05/31/2010	GW	045-18276	MAHAFFEY PA 421-36	PR	✕
301776	WELL	PR	05/31/2010	GW	045-18277	MAHAFFEY PA 22-36	PR	✕
301777	WELL	PR	05/31/2010	GW	045-18278	MAHAFFEY PA 322-36	PR	✕

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location****Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY			
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			
CONTAINERS	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: 970-285-9377

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WEEDS	SATISFACTORY	Dead weed debris along well heads fencing. Remove weed debris.		
TRASH	SATISFACTORY			

**Spills:**

Inspector Name: LONGWORTH, MIKE

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
TANK BATTERY	SATISFACTORY			
SEPARATOR	SATISFACTORY			
<b>Equipment:</b>				
Type: Horizontal Heated Separator	# 16	Satisfactory/Action Required:	SATISFACTORY	
Comment				
Corrective Action				Date:
Type: Ancillary equipment	# 2	Satisfactory/Action Required:	SATISFACTORY	
Comment	Chemical containers at wells			
Corrective Action				Date:
Type: Bird Protectors	# 8	Satisfactory/Action Required:	SATISFACTORY	
Comment				
Corrective Action				Date:
Type: Plunger Lift	# 16	Satisfactory/Action Required:	SATISFACTORY	
Comment				
Corrective Action				Date:

<b>Facilities:</b>				
<input type="checkbox"/> New Tank		Tank ID: _____		
Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST	,
S/AR	SATISFACTORY		Comment: Air id 045-2073-002	
Corrective Action:				Corrective Date:

<b>Paint</b>	
Condition	Adequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

<b>Facilities:</b>				
<input type="checkbox"/> New Tank		Tank ID: _____		
Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST	,

Inspector Name: LONGWORTH, MIKE

S/AR	SATISFACTORY	Comment:	Air id 045-2073-002		
Corrective Action:					Corrective Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Corrective Action					Corrective Date
Comment					
<b>Facilities:</b> <input type="checkbox"/> New Tank Tank ID: _____					
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST	,	
S/AR	SATISFACTORY	Comment:	Air id 045-2073-001		
Corrective Action:					Corrective Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Corrective Action					Corrective Date
Comment					
<b>Venting:</b>					
Yes/No	NO				
Comment					
<b>Flaring:</b>					
Type		Satisfactory/Action Required			
Comment:					
Corrective Action:					Correct Action Date:

**Predrill**

Location ID: 383329

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

S/AR: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Date: \_\_\_\_\_

**Wildlife BMPs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Date: \_\_\_\_\_

Comment: \_\_\_\_\_

**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 301762 Type: WELL API Number: 045-18263 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 301763 Type: WELL API Number: 045-18264 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 301764 Type: WELL API Number: 045-18265 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Inspector Name: LONGWORTH, MIKE

Facility ID:	301765	Type:	WELL	API Number:	045-18266	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	301766	Type:	WELL	API Number:	045-18267	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	301767	Type:	WELL	API Number:	045-18268	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	301768	Type:	WELL	API Number:	045-18269	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	301769	Type:	WELL	API Number:	045-18270	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	301770	Type:	WELL	API Number:	045-18271	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	301771	Type:	WELL	API Number:	045-18272	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	301772	Type:	WELL	API Number:	045-18273	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	301773	Type:	WELL	API Number:	045-18274	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	301774	Type:	WELL	API Number:	045-18275	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	301775	Type:	WELL	API Number:	045-18276	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	301776	Type:	WELL	API Number:	045-18277	Status:	PR	Insp. Status:	PR

Inspector Name: LONGWORTH, MIKE

**Producing Well**

Comment: **Producing well**

Facility ID: 301777 Type: WELL API Number: 045-18278 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Producing well**

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_  
DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Inspector Name: LONGWORTH, MIKE

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

#### RESTORATION AND REVEGETATION

##### Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

##### Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

#### **Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

#### **Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Compaction	Pass			
Compaction	Pass					
				MHSP	Pass	Secondary containment
Gravel	Pass					
		Culverts	Pass			
		Gravel	Pass			

Inspector Name: LONGWORTH, MIKE

Ditches	Pass					
Seeding	Pass					
Check Dams	Pass					

S/A/V: SATISFACTOR                      Corrective Date: \_\_\_\_\_  
Y \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**    ☒ NO SURFACE INDICATION OF PIT