

Photo#1:
View North over Location



Photo#2:
View South over Location



Photo#3:
View East over Location



Photo#4:
View West over Location



Photo#5:
Gravel not Removed



Photo#6:
Sediment Collecting on Location



Photo#7:

Sediment Run On to Location.



Photo#8:

Large areas of bare ground remain.



Photo#9:

Photo#10:

Deep Gullies have formed across Location.

