

Photo#1:
View North over Location Center



Photo#2:
View South over Location Center



Photo#3:
View East over Location Center



Photo#4:
View West over Location Center



April 25, 2016

Inspection Photos: Dolezal Green #1 045-06465

Photo#5:

Last year's Stands of dried litter; Thistle & Burdock infestations

Photo#6:



Photo#7:

Thistle Rosettes and Houndstongue emerging across Location

Photo#8:



Photo#9:

Weeds have established in Rodent disturbed areas



Photo#10:

Guy Anchor on Location



April 25, 2016

Inspection Photos: Dolezal Green #1 045-06465