

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
04/26/2016
Document Number:
685300414
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

| | | | | | |
|---------------------|---------------|---------------|-------------------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | <u>215571</u> | <u>325922</u> | <u>St John, William (Cal)</u> | <input type="checkbox"/> | |

Operator Information:

| | |
|-----------------------|---|
| OGCC Operator Number: | <u>10000</u> |
| Name of Operator: | <u>BP AMERICA PRODUCTION COMPANY</u> |
| Address: | <u>380 AIRPORT RD</u> |
| City: | <u>DURANGO</u> State: <u>CO</u> Zip: <u>81303</u> |

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|-----------------------|
| Beebe, Sabre | 970-375-7530 | Sabre.Beebe@bp.com | SW Inspection Reports |
| Labowskie, Steve | | steve.labowskie@state.co.us | COGCC |
| Inspections, All | | SanJuanCOGCC@bp.com | SW Inspection Reports |

Compliance Summary:

| QtrQtr: | <u>NWSE</u> | Sec: | <u>20</u> | Twp: | <u>35N</u> | Range: | <u>7W</u> |
|------------|-------------|------------|-------------|-------------------------------|------------|----------------|-----------------|
| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
| 03/09/2016 | 685200057 | PR | IO | AR | I | | No |
| 02/28/2016 | 685300080 | PR | WO | SATISFACTORY | | | No |
| 08/25/2015 | 680600093 | PR | PR | SATISFACTORY | I | | No |
| 05/20/2015 | 674900555 | PR | EI | SATISFACTORY | | | No |
| 03/06/2012 | 661700165 | PR | PR | SATISFACTORY | | | No |
| 04/16/2009 | 200208718 | PR | PR | SATISFACTORY | | | No |
| 08/08/2006 | 200101674 | PR | PR | SATISFACTORY | | Pass | No |
| 12/29/2004 | 200066293 | PR | PR | SATISFACTORY | | Pass | No |
| 06/17/2002 | 200028199 | PR | PR | SATISFACTORY | | Pass | No |
| 02/20/2001 | 200015187 | PR | PR | SATISFACTORY | | Pass | No |
| 11/08/1999 | 200002890 | PR | PR | SATISFACTORY | | Pass | No |
| 03/21/1997 | 500149256 | PR | PR | | | Pass | No |

Inspector Comment:

Follow up inspection. Corrective actions satisfactory completed from previous inspection document number 685200057.

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|--|
| 215571 | WELL | PR | 03/11/2016 | GW | 067-07176 | CUNDIFF C 1 | PR <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

Predrill

Location ID: 215571

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 215571 Type: WELL API Number: 067-07176 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

| | | |
|---|-------------------|-------------|
| Water Well: | Lat | Long |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ |
| Field Parameters: | | |
| | | |
| Sample Location: _____ | | |
| | | |
| Emission Control Burner (ECB): _____ | | |
| Comment: _____ | | |
| Pilot: _____ Wildlife Protection Devices (fired vessels): _____ | | |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Remnants of old landowner structure on SW corner (pile of boards and debris) is interfering with interim revegetation.

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM Unused pipe anchor marker and concrete stump off SE corner of location.

CA _____ CA Date _____

1003b. Area no longer in use? _____

Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: Dirt and gravel piles that were on the edge of location have been removed or incorporated into location.

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | MHSP | Pass | |
| Berms | Pass | Ditches | Pass | | | |
| Gravel | Pass | Gravel | Pass | | | |

S/A/V: SATISFACTOR Corrective Date: _____
Y _____

Comment: Sediment piles on the SE corner of location have been removed or incorporated into the location. Portable toilets removed from location.

CA: _____

Pits: NO SURFACE INDICATION OF PIT