

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/05/2016

Document Number:

674702692

Overall Inspection:

SATISFACTORY w/ CMT  
or AR**FIELD INSPECTION FORM**

|                     |             |        |                 |                          |             |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection       | 2A Doc Num: |
|                     | 324276      | 324276 | LONGWORTH, MIKE | <input type="checkbox"/> |             |

**Operator Information:**OGCC Operator Number: 96850Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name    | Phone        | Email                                | Comment                 |
|-----------------|--------------|--------------------------------------|-------------------------|
| Inspection, WPX | 970-263-2716 | COGCCInspectionReports@wpxenergy.com | WPX Inspection Mail Box |

**Compliance Summary:**QtrQtr: SWSW Sec: 7 Twp: 7S Range: 96W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 06/02/2015 | 674701478 |            |             | SATISFACTORY                  |          |                | No              |
| 09/18/2014 | 674700329 |            |             | SATISFACTORY                  |          |                | No              |

**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|-------------------------------------|
| 272899      | WELL | PR     | 11/28/2004  | GW         | 045-10191 | FEDERAL GM 14-7 | PR          | <input checked="" type="checkbox"/> |

**Equipment:**Location Inventory

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

| <b>Lease Road:</b> |                              |   |   |            |
|--------------------|------------------------------|---|---|------------|
| Type               | Satisfactory/Action Required | comment   | Corrective Action                                   | Date       |
| Access             | <b>ACTION REQUIRED</b>       | Road needs maintained from Caerus location to entrance of location. | Maintain and repair access roads per Rule 604.c.(2) | 06/06/2016 |

| <b>Signs/Marker:</b> |                              |  |                                       |                   |
|----------------------|------------------------------|--|---------------------------------------|-------------------|
| Type                 | Satisfactory/Action Required | Comment  | Corrective Action                     | CA Date           |
| TANK LABELS/PLACARDS | <b>ACTION REQUIRED</b>       | Labels have peeled off of the outside tanks in tank battery. | Install sign to comply with rule 210. | <b>07/06/2016</b> |
| CONTAINERS           | SATISFACTORY                 |  |                                       |                   |
| BATTERY              | SATISFACTORY                 |  |                                       |                   |
| WELLHEAD             | SATISFACTORY                 |  |                                       |                   |

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: **970-285-9377**

Corrective Action: \_\_\_\_\_

| <b>Good Housekeeping:</b> |                              |         |                   |         |
|---------------------------|------------------------------|---------|-------------------|---------|
| Type                      | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| TRASH                     | SATISFACTORY                 |         |                   |         |

| <b>Spills:</b>   |      |        |                   |         |
|--|------|--------|-------------------|---------|
| Type   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

| <b>Fencing/:</b> |                              |         |                   |         |
|------------------|------------------------------|---------|-------------------|---------|
| Type             | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| TANK BATTERY     | SATISFACTORY                 |         |                   |         |
| WELLHEAD         | SATISFACTORY                 |         |                   |         |
| SEPARATOR        | SATISFACTORY                 |         |                   |         |

| Equipment:                        |                            |                               |              |       |
|-----------------------------------|----------------------------|-------------------------------|--------------|-------|
| Type: Bird Protectors             | # 2                        | Satisfactory/Action Required: | SATISFACTORY |       |
| Comment                           |                            |                               |              |       |
| Corrective Action                 |                            |                               |              | Date: |
| Type: Ancillary equipment         | # 1                        | Satisfactory/Action Required: | SATISFACTORY |       |
| Comment                           | Chemical container at well |                               |              |       |
| Corrective Action                 |                            |                               |              | Date: |
| Type: Horizontal Heated Separator | # 1                        | Satisfactory/Action Required: | SATISFACTORY |       |
| Comment                           |                            |                               |              |       |
| Corrective Action                 |                            |                               |              | Date: |

Inspector Name: LONGWORTH, MIKE

|                    |     |  |
|--------------------|-----|--|
| Type: Plunger Lift | # 1 | Satisfactory/Action Required: SATISFACTORY |
| Comment            |     |  |
| Corrective Action  |     | Date:                                      |

**Facilities:** ☐ New Tank Tank ID: \_\_\_\_\_

| Contents | # | Capacity | Type      | SE GPS |
|----------|---|----------|-----------|--------|
| METHANOL | 1 | <50 BBLS | STEEL AST | ,      |

|                    |              |                  |  |
|--------------------|--------------|------------------|--|
| S/AR               | SATISFACTORY | Comment:         |  |
| Corrective Action: |              | Corrective Date: |  |

Paint

|           |          |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |

|                   |  |                 |  |
|-------------------|--|-----------------|--|
| Corrective Action |  | Corrective Date |  |
| Comment           |  |                 |  |

**Facilities:** ☐ New Tank Tank ID: \_\_\_\_\_

| Contents | # | Capacity | Type             | SE GPS |
|----------|---|----------|------------------|--------|
|          | 1 | 300 BBLS | HEATED STEEL AST | ,      |

|                    |              |                  |  |
|--------------------|--------------|------------------|--|
| S/AR               | SATISFACTORY | Comment:         |  |
| Corrective Action: |              | Corrective Date: |  |

Paint

|           |          |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |

|                   |  |                 |  |
|-------------------|--|-----------------|--|
| Corrective Action |  | Corrective Date |  |
| Comment           |  |                 |  |

**Facilities:** ☐ New Tank Tank ID: \_\_\_\_\_

| Contents | # | Capacity | Type      | SE GPS |
|----------|---|----------|-----------|--------|
|          | 2 | 300 BBLS | STEEL AST | ,      |

|                    |              |                  |  |
|--------------------|--------------|------------------|--|
| S/AR               | SATISFACTORY | Comment:         |  |
| Corrective Action: |              | Corrective Date: |  |

Paint

|           |          |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) \_\_\_\_\_

Inspector Name: LONGWORTH, MIKE

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |

|                   |  |                 |  |
|-------------------|--|-----------------|--|
| Corrective Action |  | Corrective Date |  |
| Comment           |  |                 |  |

**Venting:**

|         |                         |
|---------|-------------------------|
| Yes/No  | YES                     |
| Comment | Braden is open to vent. |

**Flaring:**

|                    |  |                              |  |
|--------------------|--|------------------------------|--|
| Type               |  | Satisfactory/Action Required |  |
| Comment:           |  |                              |  |
| Corrective Action: |  | Correct Action Date:         |  |

**Predrill**

Location ID: 324276

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

**S/AR:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 272899 Type: WELL API Number: 045-10191 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_

Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_

Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_

CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_

CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_

CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_

CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_

Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_

Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: LONGWORTH, MIKE

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Seeding          | Pass            |                         |                       |               |                          |         |
|                  |                 |                         |                       | MHSP          | Pass                     |         |
| Berms            | Pass            |                         |                       |               |                          |         |

S/A/V: **ACTION REQUIRED** Corrective Date: **06/06/2016**

Comment: \_\_\_\_\_

CA: **Maintain BMPs on access road.**

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                       | URL   |
|--------------|-----------------------------------|---|
| 674702693    | Missing labels and road condition | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3849437">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3849437</a> |