

# Coyote Was 4-27

Inspection Doc# 675202803

Vegetation around wellhead



Unused equipment onsite.



Unused equipment onsite.



Unused equipment/ Debris



Vegetation in evaporation  
pit. Netting is sagging to  
bottom of pit.



Tank with no signage.  
Vegetation in tank  
containment. Berm is  
damaged from wildlife.

