

Final Reclamation Inspection

5/5/2016

Operator: Klabzuba

Location ID: 393690

Morgan County, CO

SWNE Section 12 T1N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



Figure 1: Photo of GPS confirming location.



Figure 2: Photo taken from location, facing north.



Figure 3: Photo taken from location, facing east



Figure 4: Photo taken from location, facing south



Figure 5: Photo taken from location, facing west



Figure 6: Photo of starting point for the disturbance transect, facing north.



Figure 7: Photo of the 50 point on the disturbance transect, facing west.



Figure 8: Photo of the 50 point on the disturbance transect, facing east.



Figure 9: Photo of the 50 point on the disturbance transect.



Figure 10: Photo of ending point for the disturbance transect, facing south.



Figure 11: Photo of starting point for the reference transect, facing west.



Figure 12: Photo of the 50 point on the reference transect, facing south



Figure 13: Photo of the 50 point on the reference transect, facing south



Figure 14: Photo of the 50 point on the reference transect



Figure 15: Photo of the ending point for the reference transect, facing east.



Figure 16: Photo taken from location. Photo shows Musk Thistle (*Carduus nutans*) rosette on location. This is a List B Colorado State Noxious Weed and needs to be removed.