

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2016

Document Number:

673403174

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	257847	313113	Waldron, Emily	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10323Name of Operator: ENTEK GRB LLCAddress: 165 SOUTH UNION #366City: LAKEWOOD State: CO Zip: 80228

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
stocks, kristen	303-282-4633	KStocks@entekenergy.com	

Compliance Summary:QtrQtr: SESW Sec: 13 Twp: 12N Range: 89W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/20/2014	673401427	PR	SI	SATISFACTORY			No
12/10/2013	673400151	PR	PR	SATISFACTORY			No
10/22/2013	673400027	PR	PR	ACTION REQUIRED	F		No
04/25/2012	662300413	PR	PR	ACTION REQUIRED			No
11/04/2010	200283418	PR	PR	ACTION REQUIRED			Yes
04/20/2006	200093199	PR	PR	SATISFACTORY		Pass	No
09/28/2003	200048876	ID	SI	ACTION REQUIRED		Fail	No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
257847	WELL	PR	05/06/2010	GW	081-06986	ROBIDOUX 13-12-89 1	SI	<input checked="" type="checkbox"/>
268119	PIT	AC	06/02/2003		-	ROBIDOUX 13-12-89	AC	<input type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: **303-282-4933**

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type: Horizontal Separator	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:
Type: Deadman # & Marked	# 4	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:

Venting:

Yes/No	NO
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 257847

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 257847 Type: WELL API Number: 081-06986 Status: PR Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

S/A/V: SATISFACTORY CA Date: _____

CA: _____

Comment: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Date: _____

Inspector Name: Waldron, Emily

Corrective Action: _____		
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____		Depth to Ground Water: _____
<u>Water Well:</u>		
DWR Receipt Num: _____	Owner Name: _____	GPS : _____
<u>Field Parameters:</u>		
Sample Location: _____		
Emission Control Burner (ECB): _____		
Comment: _____		
Pilot: _____	Wildlife Protection Devices (fired vessels): _____	
<u>Reclamation - Storm Water - Pit</u>		
<u>Interim Reclamation:</u>		
Date Interim Reclamation Started: _____		Date Interim Reclamation Completed: _____
Land Use: _____		
Comment: _____		
1003a. Waste and Debris removed? _____		
CM _____		
CA _____		CA Date _____
Unused or unneeded equipment onsite? _____		
CM _____		
CA _____		CA Date _____
Pit, cellars, rat holes and other bores closed? _____		
CM _____		
CA _____		CA Date _____
Guy line anchors marked? _____		
CM _____		
CA _____		CA Date _____
1003b. Area no longer in use? _____		Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____		
1003d. Drilling pit closed? _____		Subsidence over on drill pit? _____
Cuttings management: _____		
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____		
Production areas have been stabilized? _____		Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION		
<u>Cropland</u>		
Top soil replaced _____	Recontoured _____	Perennial forage re-established _____
<u>Non-Cropland</u>		

Inspector Name: Waldron, Emily

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Gravel	Pass					
		Ditches	Pass			
		Sediment Traps	Pass			
		Culverts	Pass			
Compaction	Pass					
Berms	Pass					
		Compaction	Pass			

S/A/V: SATISFACTOR

Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT